

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	State ☒ Fee ☐
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name Bell Lake
2. Name of Operator CONOCO INC.	8. Farm or Lease Name Bell Lake Unit
3. Address of Operator P. O. Box 460, Hobbs, N.M. 88240	9. Well No. 11
4. Location of Well UNIT LETTER <u>N</u> <u>790</u> FEET FROM THE <u>South</u> LINE AND <u>2265</u> FEET FROM THE <u>West</u> LINE, SECTION <u>31</u> TOWNSHIP <u>23S</u> RANGE <u>34E</u> NMPM.	10. Field and Pool, or Wildcat Bell Lake Bone Springs
15. Elevation (Show whether DF, RT, GR, etc.)	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER <u>blast frac</u> ☒	CASING TEST AND CEMENT JOBS ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU. CO to 8782'. Set RBP @ 8670'. Run CBL & variable density log & locate top of crnt. while going in hole. Log from 8665' - 8000' & pull up hole & log from 200' below the TOC to 200' above the top. If wellbore is clean to PBTD, dump 95 gals of limestone pea gravel down open ended tbg. If wellbore is not clean to PBTD but below 8782', dump a volume of pea gravel calc. as follows: (Top of fill - 8772') x .9764 = # gals of pea gravel. Place 115 gals Tovex 836 explosive across interval from 8772' - 8654'. Load wellbore to the surf. w/200 bbls TFW. Set detonating bombs above the explosive @ 8654' w/clocks set for ample time to place Cal-seal stem & evacuate location. Place 10 gals limestone pea gravel on top of bombs. Place 101 gals Cal-seal on top of gravel. Leave well open & piped to pit. DO all of Cal-seal to the pea gravel @ 8665' w/stable foam. Run prod. equipment & place well on test.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Ann Bull TITLE Administrative Supervisor DATE 5/23/85

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ DATE MAY 28 1985

CONDITIONS OF APPROVAL, IF ANY: