

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-71

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Anadarko Production Company	8. Farm or Lease Name M.W. Coll
3. Address of Operator P.O. Box 806 Eunice, New Mexico 88231	9. Well No. 3
4. Location of Well UNIT LETTER N, 660 FEET FROM THE South LINE AND 1980 FEET FROM THE West LINE, SECTION 26 TOWNSHIP 22S RANGE 37E NMPM.	10. Field and Pool, or Wildcat Langlie Mattix
15. Elevation (Show whether DF, RI, GR, etc.) 3320' GL 3334' DF	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER Additional perforating & stimulation ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPERATIONS ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1709.

1. RUPU, TOH w/prod rods, pump & tbg.
2. TIH w/4-3/4" bit. CO to PBTD 3718'. Drill float collar & cement from shoe jt. to 3730'. TOH.
3. RU Wellex & perforate additional ^{Perforate} zone w/2 SPF, 1/2" holes 3559'-63', 3565'-70', 3574'-81'.
4. Acidize all perms w/2000 gals NE-FE acid.
5. RU Western Co. & fracture treat w/45,000 gals Mini-Max 3-40 w/78,000# 20/40 sand & 45,000# 10/20 sand. SI overnight.
6. Wash sand from well bore.
7. Put back on pump.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature]
ORIGINAL SIGNED BY Field Foreman
DISTRICT SUPERVISOR

TITLE Field Foreman

DATE June 22, 1983

TITLE

DATE

RECEIVED

JUN 24 1983

O.C.D.
HOBBS OFFICE