## STATE OF NEW MEXICO CNERGY AND MINERALS DEPARTMENT

we, or corics acceives	T	
DISTRIBUTION		
SANTA FE		
FILE		
U.S.O.S.		
LAND OFFICE		
02484708	$\top$	

## OIL CONSERVATION DIVISION

we, or corics acceives	OIL CONSERVATION DIVISION	Form C-103 ·
DISTRIBUTION	P. O. BOX 2088	Revised 10-1-78
SANTA FE	SANTA FE, NEW MEXICO 87501	
FILE	•	Sa. Indicate Type of Lease
U.S.O.S.		State X Foo
LAND OFFICE		5. State Oil 6 Gas Lease No.
OPERATOR		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	API No. 30-025-24380	P-33440
SHINDS	V NOTICES AND REPORTS ON WELLS	
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL ON TO DEFPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  (DO NOT USE THIS FORM FOR PROMIT - " (FORM C-101) FOR SUCH PROPOSALS.)		
USE "APPLICAT	10H FOR PERMIT 1 TORM COTOTY FOR SECH PROPOSICES.	7. Unit Agreement Name
·		
OIL X WELL	OTHER+	8. Farm or Lease Name
Name of Operator .		
Didlides Dotroloum Co	mn 2 n 3 i	Sims
Phillips Petroleum Company  1. Address of Operator		9. Well No.
Room 401, 4001 Penbrook, Odessa, TX 79762		, 7
		10. Field and Pool, or Wildcat
:. Location of Well	2210	
C	380 PEET FROM THE NORTH LINE AND 2310	ET FROM Tubb
west	ON	
THE LINE, SECTI	OH TOWNSHIP RANGE	
mmmmm	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	3226' GR, 3337' RKB	Lea
	11111 3220 GR, 3337 Idds	
Check	Appropriate Box To Indicate Nature of Notice, Report	or Other Data
		QUENT REPORT OF:
NOTICE OF I	TENTION TO:	•
		¬
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE ORILLING OPHS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	
	other Filed to rec	ord P&A of zone X
OTHER		÷
Secretary Completed O	perations (Clearly state all pertinent details, and give pertinent dates, is	scluding estimated date of starting any proposes
work) SEE RULE 1103.	perations (assess) state as parameters	
,		
With out ret @ 7144'	, pmpd 100 sx cmt & displaced w/24 bbls fresh	water. Pld out of ret.
	Pipe stuck, cut tbg @ 5646 & pld tbg. Tagg	
	d out fish & drilled cmt & fish from 5633'-61	
5900', tstd Tubb per	fs to 1000#, held OK. Selective perfs 5959'-	6167' in the Tubb zone
effectively cmt sqzd	and abandoned.	
•		•
	•	
	•	•
·	•	
	• .\	
		•

ORIGINAL SIGNED BY JERRY SEXTON