

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-24435
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name Cossatot I
2. Name of Operator John H. Hendrix Corporation	8. Well No. 1
3. Address of Operator P. O. Box 3040, Midland, TX 79702-3040	9. Pool name or Wildcat Brunson Drinkard-Abo, S. Wantz Granite Wash
4. Well Location Unit Letter <u>D</u> : <u>990</u> Feet From The <u>North</u> Line and <u>330</u> Feet From The <u>West</u> Line Section <u>13</u> Township <u>22S</u> Range <u>37E</u> NMPM <u>Lea</u> County <u></u>	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3336' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☒ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set CIBP at 7100' + 20' cement to abandon Wantz Granite Wash perfs. fr. 7126' - 7316'.
2. Set CIBP at 6210' + 20' cement to abandon Brunson; Drinkard-Abo, South perfs. fr. 6233 - 6968'.
3. Perforate selective interval in Blinbry fr. 5420 - 5560'.
4. Acidize and treat.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ronnie H. Westbrook TITLE Vice-President DATE 4/25/96

TYPE OR PRINT NAME Ronnie H. Westbrook (915) TELEPHONE NO. 684-6631

(This space for State Use)

APPROVED BY [Signature] TITLE  DATE

CONDITIONS OF APPROVAL, IF ANY:

ORIGINAL SIGNED  
DISTRICT I SEAL

MAY 13 1996