

32. Acid, shot, Fracture, Cement Squeeze, Etc.

- 1-6-74 Perf. 4307'-12', 4419'-22', 4500'-05'
4524'-28'. Breakdown perfs w/500 GA
15% teg. Treat w/3000 gals 20% acid.
Swab 100% sulfur water. Set retainer at
4000' and squeezed w/400 sks cmt. Drld
out to 4260'.
- 1-15-74 Perf 4207'-12', 4222'-26'. Breakdown
perfs w/500 GA 15% reg. Swab tested
100% sulfur with fluid level @ 2000'.
Set retainer @ 4161' and squeezed w/275
sks.
- 1-17-74 Perf 4070'-79', 4094'-98-, 4121'-28'.
Breakdown perfs w/250 GA 15% reg. Swab
tested 100% sulfur water. Set retainer
@ 4058'. Squeezed w/11 sks cement.
- 1-22-74 Perf 3944'-50', 3975'-78', 3988'-93',
4002'-05', 4012'-16'. Breakdown perfs
w/1000 GA 15% reg. Swab tested 100%
sulfur water. Set retainer @ 3930'.
Squeezed w/150 sks cement.
- 1-25-74 Perf w/1 JS @ each 3735', 3753', 3778',
3780', 3791', 3797', 3801', 3804', 3839', 3857',
3867', 3871', 3876', & 3885'. Breakdown
perfs w/700 GA 15% reg. & 12 ball sealers.
Fracture treat using 60,000 gals. 9#
gelled brine and 62,000# sand in 3 stages.