

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-4-85

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- <u>Water Injection</u>		7. Unit Agreement Name <u>South Eunice Unit</u>
2. Name of Operator <u>Conoco Inc.</u>		8. Farm or Lease Name <u>South Eunice Unit</u>
3. Address of Operator <u>P. O. Box 460, Hobbs, New Mexico 88240</u>		9. Well No. <u>65</u>
4. Location of Well UNIT LETTER <u>O</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>28</u> TOWNSHIP <u>22S</u> RANGE <u>36E</u> NMPM.		10. Field and Pool, or Wildcat <u>S. Eunice 7 Rvs Queen</u>
15. Elevation (Show whether DF, RT, GR, etc.)		12. County <u>Lea</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <u>clean out</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

MIRU on 9-1-84. Tag @ 3562'. CO to 3580'. Mill out from 3580' to 3800'. Set pkr. Acidize with 11.9 bbls. 15% HCL-NE-FE. Flush with 30 bbls. 9# brine. Place well on injection. Inj. 45 BWPD @ 940 psi.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Danilo D. Paul</u>	TITLE <u>Administrative Supervisor</u>	DATE <u>11/8/84</u>
APPROVED BY <u>Eddie W. Seay</u>	TITLE <u>Oil & Gas Inspector</u>	DATE <u>NOV 13 1984</u>