

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPlicate
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. NM-68820	
2. NAME OF OPERATOR RAY WESTALL		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR Box 4 Loco Hills NM 88255		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660 FNL & 660' FEL Unit A		8. FARM OR LEASE NAME FEDERAL 19	
14. PERMIT NO. 30-025-24676		9. WELL NO. 1	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3503 GR		10. FIELD AND POOL, OR WELDCAT N. Bill Lake Delaware UNDECAT DELAWARE	
		11. SEC., T., S., M., OR BLK. AND SURVEY OR AREA 19-T 23S-R34E	
		12. COUNTY OR PARISH LEA	
		13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) RE-ENTER	
(Other) <input type="checkbox"/>		(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

SEE ATTACHED DRILLING REPORT

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Geologist A

DATE

8/30/92

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

RECEIVED

SEP 16 1992

OCD HOBBS OFFICE

Ray Westall Operating, Inc.
Federal 19 #1
Section 19,
Township 23 South, Range 34 East
Lea County, New Mexico

6/29/92 Move in L & M rig #2, spud re-entry at 8:00 AM
6/30/92 Milling on top of 8 5/8" csng at 3037'.
7/1/92 Ran 74 jts 8 5/8" csng with 43" 10 3/4" slip jt.
7/2/92 Milling on junk at 3433'.
7/3/92 Milling on junk at 3453'.
7/4/92 Drlg on cement at 4258'.
7/5/92 Milling on junk at 4261'.
7/6/92 Drilling on cement at 4291'.
7/7/92 Milling on top of 5 1/4" csng at 4437'.
7/8/92 Move off Dlg Rig.
7/9/92 Rig up reverse unit and pulling unit prep to
clean out 5 1/2" csng.
7/10/92 Drlg out cmt @ 4440'.
7/11/92 Drlg CIBP @ 7600'.
7/12/92 SD
7/13/92 Drlg on CIBP @ 7600'.
7/14/92 Logging with Atlas SBT/CCL, CNL/GR, PDK-100.
7/15/92 Finished logging, perforated 8256-87 with 21
bullets.
7/16/92 Acid perfs with 1500 gal 15% HCl. Broke at
2000# AIR 3 bpm at 1700#, swab back load.
small show gas.
7/17/92 SITP 0# 1000' load wtr tr oil.
7/18/92 SD
7/19/92 SD
7/20/92 Perf 8174-8192, 7690-7730.
7/21/92 Acid perfs 8174-8192 with 1000 gal 15% SRA
Swab no shows.
7/22/92 Acid perfs 7690-7730 with 1500 gal 15% SRA.
Swab no shows.
7/23/92 Packer leaking, trp tubing.
7/24/92 Reset packer, swab perfs 8256-87. Re-acid
with 1000 gal 15% SRA. Swab tr show oil.
7/25/92 SD
7/26/92 SD
7/27/92 Prep to perforate 6856-83.
7/29/92 Prep to frac. Ystd perforated 21 shots 6856-83.
Acid with 1000 gal 15% HCl. Swab good show oil.
7/30/92 Swabbing back load. Ystd Frac with 20,000 gal
2% KCl wtr 46000# 16/30 sd.
7/31/92 Stuck swab in hole.
8/1/92 Pull packer and tubing
8/2/92 Swabbing
8/3/92 FL 1000' swabbing with tr show.
8/4/92 FL 500' first 500' 100% oil swabbing.
8/5/92 Swabbing FL 700' first 600' oil. Swabbing
20% oil.
8/6/92 Pulling packer. Prep to run rods and tubing.
8/7/92 S.I. WO pumpjack & production facilities.

RECEIVED

SEP 16 1992

OCD HOBBS OFFICE