H OF COPIES RECEIVED]		Form C-103	
DISTRIBUTION	1		Supersedes Old	
├ ·		L CONSERVATION COMMISSIO	C-102 and C-103 Effective 1-1-65	
		E CONSERVATION COMMISSION		
FILE	4		5a. Indicate Type of Lease	
U.S.G.S.	-			x
LAND OFFICE	4			
OPERATOR			5, State Oil & Gas Lease No.	
(DO NOT USE THIS FORM FOR PR	RY NOTICES AND REPOR	RTS ON WELLS or plug back to a different reserv) for such proposals.)	01R.	
1.			7. Unit Agreement Name	- <u>> </u>
OIL GAS WELL	OTHER.		Skelly Penrose "A"	Inft
2. Name of Operator			8. Farm or Lease Name	
Skelly 011 Company			Skelly Penrose "A"	Tod +
3. Address of Operator			9. Well No.	
			4.5	
P. O. Box 1351, Midland	, lexas /9/01		65 10. Field and Pool, or Wildcat	
UNIT LETTER K. 13	30 FEET FROM THE	South LINE AND 1330	FEET FROM Langlie-Mattix	
				7777
				III
THE West LINE, SECTI	10N 33 TOWNSHIP	225 RANGE 37E	NMPM.	
THE West LINE, SECTI			NMPM.	
THE LINE, SECTI		22S RANGE 37E	NMPM. 12. County	
THE West LINE, SECTI			12. County	
	15, Elevation (Show	whether DF, RT, GR, etc.) 2941 [•] KB	12. County Les	
16. Check	15. Elevation (Show Appropriate Box To Indi	whether DF, RT, GR, etc.) 2941 ' KB icate Nature of Notice, Re	12. County Lea port or Other Data	
16. Check	15, Elevation (Show	whether DF, RT, GR, etc.) 2941 ' KB icate Nature of Notice, Re	12. County Les	
16. Check NOTICE OF I	Appropriate Box To Indi NTENTION TO:	whether DF, RT, GR, etc.) 2941[†] KB icate Nature of Notice, Re SUI	12. County Lea port or Other Data BSEQUENT REPORT OF:	
16. Check	15. Elevation (Show Appropriate Box To Indi	Dow REMEDIAL WORK	12. County 12. County Lea port or Other Data BSEQUENT REPORT OF: Altering casing	
16. Check NOTICE OF I	Appropriate Box To Indi NTENTION TO:	Dow Development of Notice, Rej SUI DON REMEDIAL WORK COMMENCE DRILLING OPNS	12. County 12. County Lea port or Other Data BSEQUENT REPORT OF: ALTERING CASING PLUG AND ABANDONME	
16. Check NOTICE OF II	Appropriate Box To Indi NTENTION TO:	Dowhether DF, RT, GR, etc.) 2941 KB icate Nature of Notice, Rep SUI don Remedial work commence drilling opns casing test and cement	12. County I.es port or Other Data BSEQUENT REPORT OF: ALTERING CASING PLUG AND ABANDONME JQB	
16. Check NOTICE OF II PERFORM REMEDIAL WORK	15, Elevation (Show Appropriate Box To Indi NTENTION TO: Plug and abank	Dow hether DF, RT, GR, etc.) 2941 KB icate Nature of Notice, Rej SUI DON REMEDIAL WORK COMMENCE DRILLING OPNS CASING TEST AND CEMENT OTHER Perforat	12. County I.ee port or Other Data BSEQUENT REPORT OF: ALTERING CASING PLUG AND ABANDONME JGB Ce & treat Queen perfs.	
16. Check NOTICE OF II PERFORM REMEDIAL WORK	15, Elevation (Show Appropriate Box To Indi NTENTION TO: Plug and abank	Dowhether DF, RT, GR, etc.) 2941 KB icate Nature of Notice, Rep SUI don Remedial work commence drilling opns casing test and cement	12. County I.ee port or Other Data BSEQUENT REPORT OF: ALTERING CASING PLUG AND ABANDONME JGB Ce & treat Queen perfs.	NT
16. Check NOTICE OF II PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	15, Elevation (Show Appropriate Box To Indi ntention to: plug and abani change plans	Downer DF, RT, GR, etc.) 2941 KB icate Nature of Notice, Rej SUI DON REMEDIAL WORK COMMENCE DRILLING OPNS CASING TEST AND CEMENT OTHER Perforat 3548-359	12. County I.ee port or Other Data BSEQUENT REPORT OF: ALTERING CASING PLUG AND ABANDONME JGB Ce & treat Queen perfs.	_ X _

- 1) Moved in workover rig 8-29-74.
- 2) Perforated 5-1/2" and 5-9/16" OD casing with one 0.45" diameter hole at 3548', 3558', 3564', 3571', 3578', 3587' 3591', 3627', 3637', 3642', 3647', 3649', 3664', 3667', 3672', 3676', and 3694' (Total 17 shots).
- 3) Spotted 150 gallons 15% NE acid over Queen perfs. 3548-3694'. Treated with 1500 gallons 15% NE acid, 55 gallons scale inhibitor, 110 gallons corrosion inhibitor, 50,000 gallons 9.2# gelled brine, 75,000# 20/40 sand in three stages, 1800# rock salt, 900# benzoic acid flakes, and 30 ball sealers. Flushed with 25 bbls. water.
- 4) Set retrievable bridge plug at 3612' and spotted 2 sacks 20/40 sand on top of plug.
- 5) Squeezed Queen perfs. 3548-3591' with 100 sacks Chemcomp.
- Tested squeezed perfs. to 3000# for 1 hour, held okay. 6)
- Cleaned out 3670-3703'. 7)
- Squeezed Queen perfs. 3627-3694' with 150 sacks Chemcomp. 8)

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

- Tested squeezed perfs. 1000# for 1 hr., held okay. 9)
- Perforated 5-1/2" & 5-9/16" OD casing with one 0.45" diameter hole at 3636', 3638', 3648', 10) and 3673' (Total 4 shots).
- Squeezed Queen perfs. 3636-3673' with 200 sacks Class "C" cement, 0.5% CFR-2, 2% CaCl. 11) WOC 24 hours.

(Continued on Back)

(Signed) D. R. C.O	D. R. Crow	Lead Clerk	10-25-74
APPROVED BY John W, CONDITION OF APPROVAL, IF	Runyan	TITLE	DATE

- 12) Spotted 150 gallons 15% NE acid 3506-3650'.
- 13) Perforated 5-1/2" & 5-9/16" OD casing with one 0.45" diameter hole at 3636', 3638', and 3648' (Total 3 shots).
- 14) Treated Queen perfs. 3636-3648' with 27 bbls. lease oil.
- 15) Squeezed Queen perfs. 3636-3648' with 100 sacks Class "C" cement, 2% CaCl.
- 16) Spotted 200 gallons 15% NE acid 3396-3600'.
- 17) Perforated 5-1/2" & 5-9/16" OD casing with one 0.38" diameter hole at 3548', 3558', 3564', 3571', 3578', 3587', and 3591' (Total 7 shots).
- 18) Treated with 40 bbls. gelled lease oil pad, 6000 gallons gelled lease oil and 9,000# 20/40 sand. Flushed with 10 bbls. lease oil and 20 bbls formation water.
- 19) Set 110 joints (3518') 2-3/8" OD tubing at 3530'.
- 20) Well commenced producing 10-13-74 pumping Queen perfs. 3548-3591' for 1 bbl. oil, 78 bbls. water and 9 MCFGPD.