

DISTRICT I

P.O. Box 1980, Hobbs, NM 88241-1980

DISTRICT II

811 S. First Street, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 South Pacheco  
Santa Fe, New Mexico 87505

WELL API NO.	30-025-24916
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	K-2149
7. Lease Name or Unit Agreement Name	Antelope Ridge Unit
8. Well No.	#5
9. Pool Name or Wildcat	SWD; Delaware <96100>
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3540' DF

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER SWD	2. Name of Operator STRATA PRODUCTION COMPANY
3. Address of Operator P.O. BOX 1030, ROSWELL, NEW MEXICO 88202-1030	4. Well Location Unit Letter L : 2310 Feet From The South Line and 990 Feet From The West Line Section 33 Township 23 South Range 34 East NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3540' DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: Convert to SWD <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)  
SEE RULE 1103

09/08/95: MIRU. NU BOP.

09/09/95: Drill out surface plug to 120'. Test casing to 800#. Held OK. Drill out plug from 1169' to 1298'. Test casing to 750#. Held OK. Circulate hole clean.

09/11/95: Drill out plugs at 5190' and 5259' to 5386'. Tag plug at 6778'. Circulate hole clean.

09/12/95: Cement at 6778' with 338 sacks 50/50 Poz 'C' with additives. Reverse out 1 barrel cement. WOC.

09/13/95: Tag TOC at 6134'. TIH with tubing. ND BOP. NU wellhead.

09/18/95: Acidize with 3000 gallons 7 1/2% NEFE. Flow back.

10/27/95: TIH with tubing and packer. Set packer at 5118'. Pressure test to 500# for 30 minutes. Held OK. Chart attached. 278-11275 @ 5118

11/01/95: Set pump and suction, discharge and flow lines. Start filling battery.

11/05/95: Start injection.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE	<u>Carol J. Garcia</u>	TITLE	<u>PRODUCTION RECORDS MANAGER</u>	DATE	<u>11/14/95</u>
TYPE OR PRINT NAME	<u>CAROL J. GARCIA</u>	TELEPHONE NO.	<u>505-622-1127</u>		

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

APPROVED BY		TITLE		DATE	<u>DEC 22 1995</u>
-------------	--	-------	--	------	--------------------

CONDITIONS OF APPROVAL, IF ANY:

SWD-578  
JC BA

JD