Form 9-331 (May 1963)	DEPARTME.	D STATES OF THE INTERIC GICAL SURVEY	SUBMIT IN TRIP	~\TE•	Form approved. Budget Burean No. 42-R1424. G. LEASE DESIGNATION AND SERIAL NO. 18307
(Do not use thi	NDRY NOTICES A	ND REPORTS O	N WELLS	<u>.</u>	C. IF INDIAN, ALLOTTEB OR TRIBE NAME
1. OIL GAS WELL X GAS WELL 2. NAME OF OPERATOR	OTHER	l.	S. E. C. Patr	SURVE	Antebellum Unit
	illing Co.	<del></del>	1 V 5, 100, 100, 100, 100 1 V 5, 100, 200, 100	A -XIC	8. FARM OR LEASE NAME Antebellum Unit 9. WELL NO.
see also space if be	5596, Midland Report location clearly and low.)	Texas 7970	1 NOS		2 10. FIELD AND POOL, OR WILDCAT
At surface <del>660</del> ª FNL & Lea County	1980' FEL of , New Mexico	Sec. 29, T23	S, R37E,		Wildcat 11. BBC., T., R., M., OR BLK. AND SURVET OR AREA
14. PERMIT NO.		VATIONS (Show whether DF, R	T, QR, etc.)		Sec. 29, T23S, R <del>37E</del> 12. COUNTY OR PARISH 18. STATE
16.		3514, DF 3532			Lea New Mexic
	NOTICE OF INTENTION TO:	e Box To Indicate Na			
TEST WATER SHUT- FRACTURE TREAT Shoot or acidize Repair Well (Other)	MULTIPLE ABANDON* CHANGE FL	ANB	WATER SHUT-OFF FRACTURE TREATMEN SHOOTING OR ACIDIZI (Other) (Note: Report	results o	ENT REPORT OF: REPAIRING WELL ALTERING CARING ABANDONMENT* of multiple completion on Well tion Report and Log form.)
proposed work. In nent to this work.)	well is directionally drille	ed, give subsurface location	letails, and give pertinent is and measured and true	t dates, i vertical	ncluding estimated date of starting any depths for all markers and zones perti-
The followi	ng work has been	n done to test a	nd repair well	head .	leaks of the subject well
inuary 25, 1979		cellar to check :			
ne well down.	lange and the 9 htened sufficier Found 800 psi or	tly to stop the	the well head. leakss. Called	Atter d out	found well head leaking mpted to tighten, but kill truck to blow ll truck, recovering SDON.
nuary 30, 1979 barrels of oi	: Flowed into t 1 with light BS&	ransport truck. W.	Pressure reduc	ced to	o zero after recovering
et test tank to Un	location. able to get tran	vered 90 bbls. 1	in tank in 5 hou	urs, S	nk truck, flowed 90 minute SITP 50 psi. Shut in to its were granted on
ghways due to	snow and ice.		test tank as no	permi	its were granted on
	9: SITP 400 psi Well was dead,	Dut would make	n to zero press small head from	sure i n time	in 5 hours, recovering to time. apparently
SIGNED A	Elum	7_ TITLE	gent		PATE 3-9-79
(This space for Feder APPROVED BY CONDITIONS OF AP)			APPRO MAR13	<b>VE</b> 1979	Page A
		*See Instructions on	Reverse Side DISTRI	CTENC	GINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

State or Federal office for specific instructions Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and conditioned for final inspection looking to approval of the abandonment. above pluga; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site

U.S. GOVERNMENT PRINTING OFFICE: 1963-O-605229

GPO 837-499

ł

147-151

Conclusion of Sundry Notices Dated March 9, 1979. Antebellum Unit Well No. Ratliff Drlg Co. N 

.

914414 914414

Will run 2 3/8" OD tubing and repair well head. wireline cement retainer to act as packer to be well can be repaired without killing with other fluids. set in ഗ 5/8" OD casing at about 5000'. Preparing to remove head and run

Hauled tubing to location

on other work from weather oriented down time. be assured well head could be removed for repaires without killing with other liquids., OK. February 23, 1979: Bled pressure from 100 psi to zero. Called pulling unit, waiting on unit. Unit not available due to catching up Watched well for three hours to

S. HZ. .

bore has been severely damaged by previous contact with other fluids. casing. It would damage the well substantially to kill with other liquids as the well the steel ring gaskets and run tubing to be set in a wireline retainer in the 9 5/8" OD It is proposed that the well will be killed by blowing down, remove the head, replace

Work will proceed as soon as a pulling unit is available.