

OIL CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fed <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Gulf Oil Corporation		8. Farm or Lease Name Alice Paddock
3. Address of Operator P. O. Box 670, Hobbs, NM 88240		9. Well No. 7
4. Location of Well UNIT LETTER <u>B</u> <u>750</u> FEET FROM THE <u>North</u> LINE AND <u>2310</u> FEET FROM THE <u>East</u> LINE, SECTION <u>1</u> TOWNSHIP <u>22S</u> RANGE <u>37E</u> NMPM.		10. Field and Pool, or Wildcat Wantz Granite Wash
15. Elevation (Show whether DF, RT, GR, etc.) 3359' GL		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <u>Repair Casing Pressure</u> <input checked="" type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

POH with production equipment. Set RBP at 2500', cap with 10' frac sand. Displace hole with brine. Perf 1350' with (2) 1/2" JH 180 phase. Pump down 5 1/2" casing and out 8-5/8". Break down perfs and circulate 5 1/2"-8-5/8" annulus. Set cement retainer at 1250'. Pump 300 sacks Class "C" with 2% CaCl. Squeeze 500#-750#. PO cement retainer, cap with 1 sack cement. Drill out cement retainer and cement. Wash sand off RBP and POH. GIH with tubing, rods and pump.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R.D. Patre TITLE Area Engineer DATE 9-15-81

APPROVED BY [Signature] TITLE  DATE

CONDITIONS OF APPROVAL, IF ANY: