

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-76

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator GULF OIL CORPORATION	8. Farm or Lease Name H. T. Mattern (NCT-D)
3. Address of Operator P.O. Box 670, Hobbs, NM 88240	9. Well No. 12
4. Location of Well UNIT LETTER <u>K</u> <u>2130</u> FEET FROM THE <u>South</u> LINE AND <u>1860</u> FEET FROM THE <u>West</u> LINE, SECTION <u>6</u> TOWNSHIP <u>22S</u> RANGE <u>37E</u> NMPM.	10. Field and Pool, or Wildcat Tubb & Drinkard
15. Elevation (Show whether DF, RT, GR, etc.) 3454' GL	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <u>Re-opened TA Drinkard &amp; CDH w/Tubb</u> <input checked="" type="checkbox"/>
		per Order DHC-384	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PBTD 6759'. POH w/rods & pmp. Drilled frac sd to top of CIBP @ 6442'; RIH to Drinkard PBTD @ 6759'. Ran rods & pmp & hung well on.

Well ppd 13 BO, 6 BW, 60 MCF in 24 hrs before CDH. After CDH, well ppd 45 BO, 60 BW & 80 MCF in 24 hrs.

Work performed 7-30-79 through 8-9-79.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Russell Worley TITLE Area Engineer DATE 8-14-79

APPROVED BY Orig. Signed by Jerry Sexton TITLE Dist 1, Supv. DATE AUG 15 1979

CONDITIONS OF APPROVAL, IF ANY