State of New Mexico rgy, Minerais & Natural Resources Department

Form C-101 Revised February 10, 1994 Instructions on back Submit to Appropriate District Office State Lease - 6 Copies Fee Lease - 5 Copies

AMENDED REPORT

APPLICATION FOR PERMIT TO DRILL, RE-ENTER, DEEPEN, PLUGBACK, OR ADD A ZONE

								Theophe		OGRID Number		
¹ Operator name and Address									-	² OGRID Number		
Marathon Oil Company										014021		
P.O. Box 2409										³ API Number		
Hobbs, NM									30-0	25-25131		
⁴ Pro	perty Code				5	⁵ Property Name				⁶ Well Number		
6424						Walter Lynch 6						
						e Location						
UL or lot no.	Section	Townshi	Range	Lot. Idn	Feet from	the North/	South Line	Feet from the	East/West 1	ine County		
F	1	22-5	37-Е		231	0 N	orth	1980	West	Lea		
⁸ Proposed Bottom Hole Location If Different From Surface												
UL or lot no. Section Township Range Lot. Idn Feet from						n the North/South Line Feet from the East/West line Count						
	<u>l. </u>	Propose	d Pool 1	1	<u> </u>	¹⁰ Proposed Pool 2						
Blinebry Oil & Gas												
¹¹ Work Type Code ¹²			¹² Well Type C	Well Type Code		Rotary	¹⁴ Lease Type Code		¹⁵ Ground Level Elevation			
			~ C			14		Р		22521		
16 Mul	A) کار Proposed De	Proposed Depth		A	19	<u> </u>	3353' 20 Spud Date			
	inpio		1100000	-pin	Bline	bry						
	No		7491'		<u>Grani</u> t	e Wash NA		1/31/96				
				²¹ Prop	osed Casing	and Cemen	t Progran	n				
Hole S	ize	C	asing Size	Casing	g weight/foot	Setting Depth Sacks of Ceme		nt Estimated TOC				
See Orig	rinal		C-105									
					•							
								· .				
²² Describe the proposed program. If this application is to DEEPEN or PLUG BACK give the data on the present productive zone and proposed new productive zone. Describe the blowout prevention program, if any. Use additional sheets if necessary Marathon 0il Company is proposing to recomplete to the Blinebry formation in this well. Attached is a												
procedure detailing the proposed work.												
Permit Expires 6 Months From Approval												
Permit	Expires	0.00	nna reun Lindonya	1 € ₁ 2;2 1								
Date U	inless 4	rhing	Underway	•								
Pugtuca.												
²³ I hereby certify of my knowledge	ormation gi	ven above is true	e and comp	lete to the best	OIL CONSERVATION DIVISION							
Signature:						Approved by: ORIGINAL CODALD STREW SIXTON						
Printed name: Rick Gaddis						Title: DISTRUCT I SUPERVISOR						
Title: Advanced Production Engineer						Approval Date: JAN 19 1996 Expiration Date:						
Date:		Phone:				Conditions of Approval:						
1/08/95			(50	<u>5) 393-</u>	7106 ext	Attached						

District I PO Box 1980, Hobbs, NM 88241-1980 District II 811 S. 1st Street, Artesia, NM 88210-2834 District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV PO Box 2088, Santa Fe, NM 87504-2088

OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, NM 87504-2088

Form C-101 Section 22 Walter Lynch Well No. 6

- 1. MIRU PU. POOH with rods and pump. ND wellhead and NU hydraulic BOPE. Release Lok-set packer and POOH with tubing.
- 2. Utilize packer and RBP to test BOPE to 1500 psi.
- 3. PU and RIH with 7" RBP and packer. Set RBP at ±6250'. Pull up packer to ±6220' and set. Test 7" casing and RBP to 1000 psi. Unset packer and retrieve RBP, POOH with tools.
- 4. RU wireline company and lubricator. Perforate Blinebry Formation 2 JSPF at 5862-66', 5846-58', 5766-74', 5748-62', 5724-30', 5694-98', 5682'-90', 5666-70', 5648-60', 5638-42', 5584-5610' and 5567-72' for a total of 258 holes. RD wireline company.
- 5. PU and RIH with 7" treating packer, seating nipple to ±5500'. Test tubing to 5500 psi. Set packer at ±5500'.
- 6. Acidize Blinebry perforations 5567-5862' with 6,500 gals of 15% NEFE acid using ball sealers for divert.
- 7. Release packer and RIH to 5875' and PUH to 5500' and set. RU swab and recover acid load. Release packer and POOH with tubing and packer.
- 8. RU wireline company and lubricator. Perforate Blinebry Formation with 2 JSPF at 5524-32', 5510-14', 5484-5508', 5474-78' and 5400-20' for a total of 130 holes. RD wireline company.
- 9. PU and RIH with 7" RBP and treating packer. Set RBP at ±5550' and packer at 5520'. Test casing and RBP to 1000 psi. Release packer and PUH to ±5500' and set.
- 10. Acidize Blinebry perforations 5400-5532' with 3300 gals of 15% NEFE acid using ball sealers for divert.
- 11. Release packer and RIH to ±5535', PUH to 5500' and set. RU swab and recover acid load. RD swab and release packer and retrieve RBP. POOH with tubing and tools.
- 12. RU hydrotesters. PU 3 ¹/₂" workstring with seating nipple and 7" treating packer and RIH to ±5350' and set.
- 13. RU stimulation company. Install frac valve and treating lines. Sand fracture Blinebry perforations 5400-5866' with CO_2 . Size of fracture treatment will be determined after acidizing.

Form C-101 Section 22 Walter Lynch Well No. 6 Page 2

- 14. Flow well back to recover load. If well dies, RU slickline company and tag for sand fill.
- 15. If sand fill covers perfs, RU to remove with bulldog bailer.
- 16. Release packer and POOH laying down 3 ¹/₂" workstring and packer.
- 17. RIH with mud joint, seating nipple, TAC on 2 3/8" production string. Land seating nipple at ± 5820 ' with TAC at ± 5350 '.
- 18. ND BOPE and NU wellhead.
- 19. RIH with insert pump on 3/4" and 7/8" rod string. Beam well, load and test.
- 20. RDMO PU. Start well pumping to battery on test.

rict 1 . () Pox 1980, Hobbs, NM 88241-1980 District II 811 S. 1st Street, Artesia, NM 88210-2834 District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV PO Box 2088, Santa Fe, NM 87504-2088

Largy, Millerais & Natural Resources Department

P.O. Box 2088

Santa Fe, NM 87504-2088

Revised February 10, 1994 Instructions on back Submit to Appropriate District Office State Lease - 4 Copies Fee Lease - 3 Copies

AMENDED REPORT

,

WELL LOCATION AND ACREAGE DEDICATION PLAT

¹ API Number				² Pool Code			³ Pool Name						
30-025-25131				72480				Blinebry Oil & Gas					
⁴ Property Code			⁵ Property Name						6 Well Number				
6424			Walt	6			6						
⁷ OGRID No.				8 Oper	9 Elevation			Elevation					
01402	21	Marath	on Oil Cor	npany			GL: 3353'						
¹⁰ Surface Location													
UL or lot no.	Section	I the second sec		Feet from	the	North/South Line	Feet from the East/W		est line	County			
F	F 1		37-Е		231	L O	North	1980		West Lea			
¹¹ Bottom Hole Location If Different From Surface													
UL or lot no. Section To		Township	Range	Lot. Idn	Feet from	ı the	North/South Line	Feet from the	East/West line		County		
¹² Dedicated Acres	¹³ Joint	or Infill	¹⁴ Consolidation Code ¹⁵ Order No.										
160		Y	NA					NA					
NO ALLOW	NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED												
OR A NONSTANDARD UNIT HAS BEEN APPROVED BY THE DIVISION													
						1	I hereby certify	that the	informatio	ICATION n convained herein is knowledge and belief.			
	ł			< D									
1 -2	ľ		1 al		oposed oration								
-1880!				Unit				RI					
								Signature					
1///#	8//	// 9]		Rick Gaddi	S				
760' -		33.	; ∕ /∦∢	Le	ase Bound	ary		Advanced P	roduct	ion Fr	ngineer		
			#6			1		Title	Juduct				
198	?' `A		#0					1/08/96					
hereiter	hour total							Date					
							i i	¹⁸ SURVE	YOR C	ERTIF	ICATION		
						Ì		I hereby certify the	at the we	ll location	n shown on this plat		
									supervision,	t of activity and the	ual surveys made by hat the same is true		
								and correct to the best of	A my belief.				
								<u>See Origin</u>	al Pla	t			
· · · · · · · · · · · · · · · · · · · ·								Date of Survey					
								Signature and Seal of F	rofessional S	Surveyer.			
							Certificate Number						