Submit 3 Copies to Appropriate District Office	State of New Mexico Energy, Numerals and Natural Resources Department		Form C-103 Revised March 25, 1999		
DISTRICT IOILCONSERVATION DIVISION1625 N. French Dr., Hobbs, NM 88240OILCONSERVATION DIVISIONDISTRICT IIP.O. Box 2088811 South First, Artesia NM 88210Santa Fe, New Mexico 87504-2088DISTRICT IIIDISTRICT IV2040 South Pacheco, Sante Fe, NM 87505Santa Fe, New Mexico 87504-2088			WELL API NO. 30-025-25277		
			5. Indicate Type of Lease STATE STATE 5. FEE 5. 6. State Oil & Gas Lease No. B-934		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)			7. Lease Name or Unit Agreement New Mexico S State	. Name	
1. Type of Well: Oil Well	Gas Well Other				
2. Name of Operator			8. Well No. 32		
Exxon Mobil Corporation 3. Address of Operator P.O. Box 4358 Houston TX 77210-4358			9. Pool name or Wildcat Blinebry Oil and Gas (Oil)		
4. Well Location G 2	300 Feet From The NORTH	Line and 1980	Feet From The EAST	Line	
Unit Letter: =: =:				Line Line	
Section 2	10. Elevation (Show whether 3359 GR	•	·····		
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [PULL OR ALTER CASING [OTHER:	CHANGE PLANS	REMEDIAL WORK COMMENCE DRILLIN CASING TEST AND CI OTHER: of give pertinent dates, include of proposed completion or rec	EMENT JOB	ANDONMENT	
 2-26-01 Bad casing was encountered from approximately 5464' - 6133'. 2-27-01 RIH w/6" mill, 4 drill collars & tubing. Mill got stuck @ 6087', cut tbg @ 5907'. 3-01-01 thru 3-02-01 Latch onto fish @ 5907' & jar on fish. No success. 3-03-01 Spot 1000 gals of 15% HCL across fish. 3-04-01 Recovered 1/2 jt. of tbg. & 2 drill collars. 3-05-01 Continued jarring on fish. No success. Release overshoot and POOH. 3-06-01 Mix & spot pill across perfs (5451'-5838'): 28.5 bbls fresh water, 100 lbs soda ash, 300 lbs bentonite, 250 lbs cal. carbonate & 420 lbs magna fiber. Attempted to circulate well. No success. Spot another pill. Broke circulation. 3-7-01 thru 3-12-01 Continued jarring on fish. No success. Left fish in hole (6042') 3-13-01 Set packer @ 5869' and tested existing CIBP to 1000 psi for 30 mins. Tested good. Pulled packer above top perfs. SEE ATTACHMENT FOR ADDITIONAL REMARKS 					
I hereby certify that the information above is true and		ontract Completion A	dmin	5/04/2001	
TYPE OR PRINT NAME Linda G. Kocl			TELEPHONE NO. (713) 4		
(This space for State Use)	Caig. Signed by Peul Ventz TITLE				
APPROVED BY CONDITIONS OF APPROVAL IF ANY:	ZENI Kontz TITLE		DATE	<u></u>	

Single in	Blinebry	04 G
-----------	----------	------



.