Submit 3 Copies State of New Mexico	
District Office Energy, Minerals and Natural Resources Departm	1 Ulli C
DISTRICT I 1625 N. French Dr., Hobbs, NM 88240 DISTRICT II VI South Einer Artagia NM 88210 P.O. Box 2088	Revised March 25, WELL API NO. 30-025-25299
B11 South First, Artesia NM 88210 P.O. B0X 2088 DISTRICT III Santa Fe, New Mexico 87504-2088	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	STATE STATE
DISTRICT IV 2040 South Pacheco, Sante Fe, NM 87505	6. State Oil & Gas Lease No. B-934
SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACI DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"	7. Lease Name or Unit Agreement Name
(FORM C-101) FOR SUCH PROPOSALS)	New Mexico S State
1. Type of Well:	
$\begin{array}{ccc} \text{Oil} & & \text{Gas} \\ \text{Well} & & \text{Well} & & \text{Other} \end{array}$	
2. Name of Operator	8. Well No.
Exxon Corp.	33
3. Address of Operator P.O. Box 4358	9. Pool name or Wildcat
Houston TX 77210-4358	Blinebry Oil & Gas
4. Well Location Unit Letter P: 380 Feet From The south Line and 86	50 E E T east
	Feet From The Line
Section 2 Township 22S Range 37E 10. Elevation (Show whether DR, RKB, RT, GR	NMPH Lea Count
3367 KB	
11.Check Appropriate Box to Indicate Nature of Not	tice, Report, or Other Data SUBSEQUENT REPORT OF:
11.Check Appropriate Box to Indicate Nature of Not NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
11.Check Appropriate Box to Indicate Nature of Not NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	SUBSEQUENT REPORT OF:
11.Check Appropriate Box to Indicate Nature of Not NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL W TEMPORARILY ABANDON CHANGE PLANS COMMENCE	SUBSEQUENT REPORT OF: work 🛛 Altering casing
11. Check Appropriate Box to Indicate Nature of Not NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPLETION	SUBSEQUENT REPORT OF: WORK ALTERING CASING DRILLING OPNS. PLUG & ABANDONMENT T AND CEMENT JOB
11.Check Appropriate Box to Indicate Nature of Not NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE TEMPORARILY ABANDON CHANGE PLANS COMMENCE PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST OTHER: OTHER: OTHER:	SUBSEQUENT REPORT OF: WORK ALTERING CASING DRILLING OPNS. PLUG & ABANDONMENT T AND CEMENT JOB
11. Check Appropriate Box to Indicate Nature of Not NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST OTHER: OTHER: OTHER: 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give p work) SEE RULE 1103. (For Multiple Completions: Attach wellbore diagram of propos 06/11/93 Isolate Wantz Granite perfs (7276-7530) w/CIBP set at 7050, dump (5668-5778. 06/12/93 Isolate Drinkard perfs w/RBP set at 5964. 06/14/93 Acidize perfs (5668-7588) w/4000 gal 20-28% HCL; Frac perfs w/185	SUBSEQUENT REPORT OF: WORK ALTERING CASING DRILLING OPNS. PLUG & ABANDONMENT T AND CEMENT JOB Dertinent dates, including estimated date of starting any pro- sed completion or recompletion) bail 35 sxs cmnt on top; perf ower Blinebry
11. Check Appropriate Box to Indicate Nature of Not NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST OTHER: OTHER: OTHER: 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give p work) SEE RULE 1103. (For Multiple Completions: Attach wellbore diagram of propos 06/11/93 Isolate Wantz Granite perfs (7276-7530) w/CIBP set at 7050, dump (5668-5778. 06/12/93 Isolate Drinkard perfs w/RBP set at 5964. 06/12/93 Acidize perfs (5668-7588) w/4000 gal 20-28% HCL; Frac perfs w/183 06/15/93 CO.	SUBSEQUENT REPORT OF: WORK ALTERING CASING DRILLING OPNS. PLUG & ABANDONMENT T AND CEMENT JOB Dertinent dates, including estimated date of starting any pro- sed completion or recompletion) bail 35 sxs cmnt on top; perf ower Blinebry
11. Check Appropriate Box to Indicate Nature of Not NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST OTHER: OTHER: OTHER: 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give p work) SEE RULE 1103. (For Multiple Completions: Attach wellbore diagram of propos 06/11/93 Isolate Wantz Granite perfs (7276-7530) w/CIBP set at 7050, dump (5668-5778. 06/12/93 Isolate Drinkard perfs w/RBP set at 5964. 06/14/93 Acidize perfs (5668-7588) w/4000 gal 20-28% HCL; Frac perfs w/183 06/15/93 CO. 06/15/93 CO. \$7358 06/16/93 Perf Upper Blinbry (5403-5557).	SUBSEQUENT REPORT OF: WORK ALTERING CASING DRILLING OPNS. PLUG & ABANDONMENT T AND CEMENT JOB Dertinent dates, including estimated date of starting any pro- sed completion or recompletion) bail 35 sxs cmnt on top; perf ower Blinebry
11.Check Appropriate Box to Indicate Nature of Not NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST OTHER: OTHER: OTHER: 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give p work) SEE RULE 1103. (For Multiple Completions: Attach wellbore diagram of propos 06/11/93 Isolate Wantz Granite perfs (7276-7530) w/CIBP set at 7050, dump (5668-5778. 06/12/93 Isolate Drinkard perfs w/RBP set at 5964. 06/14/93 Acidize perfs (5668-7588) w/4000 gal 20-28% HCL; Frac perfs w/183 06/15/93 CO. 06/16/93 Perf Upper Blinbry (5403-5557). 06/16/93 Perf Upper Blinbry (5403-5557). 06/17/93 Acidize w/5400 gal. 20-285 HCL; frac w/gel ave 40 bpm.	SUBSEQUENT REPORT OF: WORK ALTERING CASING DRILLING OPNS. PLUG & ABANDONMENT T AND CEMENT JOB Dertinent dates, including estimated date of starting any pro- sed completion or recompletion) bail 35 sxs cmnt on top; perf ower Blinebry
11. Check Appropriate Box to Indicate Nature of Not NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST OTHER: OTHER: OTHER: 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give p work) SEE RULE 1103. (For Multiple Completions: Attach wellbore diagram of propos 06/11/93 Isolate Wantz Granite perfs (7276-7530) w/CIBP set at 7050, dump (5668-5778. 06/12/93 Isolate Drinkard perfs w/RBP set at 5964. 06/14/93 Acidize perfs (5668-7588) w/4000 gal 20-28% HCL; Frac perfs w/183 06/15/93 CO. 06/15/93 CO. \$7358 06/16/93 Perf Upper Blinbry (5403-5557).	SUBSEQUENT REPORT OF: WORK ALTERING CASING DRILLING OPNS. PLUG & ABANDONMENT T AND CEMENT JOB Dertinent dates, including estimated date of starting any pro- sed completion or recompletion) bail 35 sxs cmnt on top; perf ower Blinebry
11.Check Appropriate Box to Indicate Nature of Not NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST OTHER: OTHER: OTHER: 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give p work) SEE RULE 1103. (For Multiple Completions: Attach wellbore diagram of propos 06/11/93 Isolate Wantz Granite perfs (7276-7530) w/CIBP set at 7050, dump (5668-5778. 06/12/93 Isolate Drinkard perfs w/RBP set at 5964. 06/12/93 GO. 06/15/93 CO. 57352 06/16/93 Perf Upper Blinbry (5403-5557). 06/16/93 Perf Upper Blinbry (5403-5557). 06/17/93 Acidize w/5400 gal. 20-285 HCL; frac w/gel ave 40 bpm. 06/18/93 CO.	SUBSEQUENT REPORT OF: WORK ALTERING CASING DRILLING OPNS. PLUG & ABANDONMENT T AND CEMENT JOB Dertinent dates, including estimated date of starting any pro- sed completion or recompletion) bail 35 sxs cmnt on top; perf ower Blinebry
11.Check Appropriate Box to Indicate Nature of Not NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST COMPLETION OTHER: OTHER: OTHER: 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give p work) SEE RULE 1103. (For Multiple Completions: Attach wellbore diagram of propos 06/11/93 Isolate Wantz Granite perfs (7276-7530) w/CIBP set at 7050, dump (5668-5778. 06/12/93 Isolate Drinkard perfs w/RBP set at 5964. 06/12/93 GO. 06/15/93 CO. 57358 06/16/93 Perf Upper Blinbry (5403-5557). 06/16/93 Perf Upper Blinbry (5403-5557). 06/17/93 Acidize w/5400 gal. 20-285 HCL; frac w/gel ave 40 bpm. 06/18/93 CO.	SUBSEQUENT REPORT OF: WORK ALTERING CASING DRILLING OPNS. PLUG & ABANDONMENT T AND CEMENT JOB Dertinent dates, including estimated date of starting any pro- sed completion or recompletion) bail 35 sxs cmnt on top; perf ower Blinebry
11.Check Appropriate Box to Indicate Nature of Not NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST COMPLETION OTHER: OTHER: OTHER: 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give p work) SEE RULE 1103. (For Multiple Completions: Attach wellbore diagram of propos 06/11/93 Isolate Wantz Granite perfs (7276-7530) w/CIBP set at 7050, dump (5668-5778. 06/12/93 Isolate Drinkard perfs w/RBP set at 5964. 06/12/93 GO. 06/15/93 CO. 57358 06/16/93 Perf Upper Blinbry (5403-5557). 06/16/93 Perf Upper Blinbry (5403-5557). 06/17/93 Acidize w/5400 gal. 20-285 HCL; frac w/gel ave 40 bpm. 06/18/93 CO.	SUBSEQUENT REPORT OF: WORK ALTERING CASING DRILLING OPNS. PLUG & ABANDONMENT T AND CEMENT JOB Dertinent dates, including estimated date of starting any pro- sed completion or recompletion) bail 35 sxs cmnt on top; perf ower Blinebry 808 gal gel, average 40 bpm. Screened out.

SIGNATURE Alles myroc		nt
TYPE OR PRINT NAME Allison C. Myrow		TELEPHONE NO. (713) 431-1213
(This space for State Use)	TITLE	DATE
CONDITIONS OF APPROVAL IF ANY:		in the second
K	1/23/1°	6/12/93 achul 10/1/13 de N-1. 1. 1 0/1.)_ +- Gui