

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-25518
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-2274
7. Lease Name or Unit Agreement Name RL
8. Well No. 1
9. Pool name or Wildcat Wildcat
10. Elevation (Show whether DF, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator C W Trainer	3. Address of Operator P O Box 755, Hobbs, NM 88241	4. Well Location Unit Letter L : 1980 Feet From The South Line and 660 Feet From The West Line Section 16 Township 23S Range 33E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)			

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Daily Operations Report ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9/1/92 Move in & rig up pulling unit. Pull 2 7/8" tubing.
9/2/92 Run tubing & set cement retainer at 9298. Squeeze perfs 5990 to 6216 with 400 sacks cement.
Shut in overnite with 1500# tubing & casing pressure.
9/3/93 Bleed off pressure. Nipple down BOP & rig down.
9/21/92 Rig up pulling unit & reverse equipment. Pull tubing & rerun with bit. Tag top of cement
at 5840. Drill cement from 5840 to 6000. Circulate hole clean.
9/22 to 9/26/92 Drill cement & cement retainer to 9427 & fall free. Circulate hole clean.
9/27/92 Shut down for Sunday.
9/28/92 Pull tubing and perf 9343-63 with 2 JSPF. Start in with packer.
9/29/92 Set packer at 9265. Treat perfs 9343-63 with 3500 gal 7.5% SRA plus 1% acetic acid.
Swab & flow load.
9/30 to 10/1/92 Swab load.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Donna Holler TITLE Agent DATE 10-2-92
TYPE OR PRINT NAME Donna Holler TELEPHONE NO. 505-393-2727

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

OCT 05 1992

RECEIVED

OCT 02 1992

ODD H05534 00000