

Submit 3 Copies  
Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-25661
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-531
7. Lease Name or Unit Agreement Name Sandwell AEQ State
8. Well No. 1
9. Pool name or Wildcat So. Rock Lake Bone Springs
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3493' GR

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

Type of Well:  
OIL WELL ☐ GAS WELL ☐ OTHER P & A Well

Name of Operator  
YATES PETROLEUM CORPORATION

Address of Operator  
105 South 4th St., Artesia, NM 88210

Well Location  
Unit Letter J : 1980 Feet From The South Line and 1980 Feet From The East Line

Section 9 Township 23S Range 35E NMPM Lea County  
10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
3493' GR

1. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
WELL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged and abandoned well as follows:

Moved in and rigged up pulling unit. Laid down rods. POOH w/tubing. Tubing parted. Rigged up wireline and 9-5/8" CIBP. RIH and set CIBP at 8700'. Nippled down wellhead flange. Ran tubing to 8700'. Flanged up wellhead and loaded hole with mud. Spot 25 sacks cement on top of CIBP at 8700'. Pulled and laid down tubing to 5700'. Spot 50 sacks cement. Pulled and laid down tubing to 3825'. Spot 50 sacks cement. Pulled 17 stands. WOC. Plug was at 9-5/8" stub. RIH w/tubing to tag cement plug. Cement was too soft. Waited 1 hour. WIH and re-tag plug at 3717'. Pulled and laid down tubing to 1950'. Spot 75 sacks cement. Pulled and laid down tubing to 565'. Spot 75 sacks cement. Pulled and laid down tubing. Left 1 joint in hole. Spot 25 sacks cement from 30' to surface. Laid down 1 joint of tubing. Cut off wellhead and installed regulation abandonment marker. **PLUGGED AND ABANDONED - FINAL REPORT.** Plugging completed 8-11-93.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE Sept. 3, 1993  
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use)

APPROVED BY Charles Perrin TITLE OIL & GAS INSPECTOR DATE OCT 27 1993  
CONDITIONS OF APPROVAL, IF ANY:

**RECEIVED**

SEP 08 1993

OCU HOLDS  
OFFICE

✓

PLUG & ABANDONMENT FORM

API NO. 20-025-25661  
OPERATOR Yates  
LEASE NAME Sandwell A E Q ST  
WELL NO. 1  
SEC. 9 TWP. 23 RANGE 35 UNIT J

Date plugging operations began - 8-5-93

Date plugging operations completed - 8-9-93

Name of plugging company - PRide

Comments: \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Signed By: Charles Person

Date: 8-11-93