

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-7

5a. Indicate Type of Lease
State ☐ For ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.

1. OIL <input checked="" type="checkbox"/> WELL GAS <input type="checkbox"/> WELL OTHER	7. Unit Agreement Name
2. Name of Operator Gulf Oil Corporation	8. Farm or Lease Name Mark
3. Address of Operator P. O. Box 670, Hobbs, NM 88240	9. Well No. 11
4. Location of Well UNIT LETTER <u>A</u> <u>430</u> FEET FROM THE <u>North</u> LINE AND <u>960</u> FEET FROM THE <u>East</u> LINE, SECTION <u>3</u> TOWNSHIP <u>22S</u> RANGE <u>37E</u> NMPM.	10. Field and Pool, or Wildcat Wantz Abo
15. Elevation (Show whether DF, RT, GR, etc.) 3393' GL	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPER. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
		OTHER <u>P&A Granite Wash, Recomplete Abo</u> <input checked="" type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

POH with production equipment. Set CIBP at 7275', dump 35' cement on CIBP. Test casing & CIBP 1000#. Perf 7221-23', 7208-10', 7194-96', 7154-56', 7125-27', 7102-04', 7090-92', 7066-68', 7052-54', 6998-7000', 6987-89', 6976-78' with (2) 1/2" JHPF. Perf 6953-55', 6928-30', 6892-94', 6848-50', 6834-36', 6804-06', 6792-94', 6758-60', 6744-46', 6720-22', 6690-92', 6678-80', 6666-68', 6630-32' with (2) 1/2" JHPF. Acidize 7052'-7223' with 360 bbls 15% NEFE HCL, (56) RCNB's. AIR 5 BPM, avg pres 4500#. Acidize 6892'-7223' with 90 bbls acid, (72) RCNB's. Avg pres 4200#, ISIP 2200#, AIR 7 BPM. Acidize 6630'-6850' with 142 bbls acid, (72) RCNB's. ISIP 400#, avg pres 4100#, AIR 6 BPM. GIH with MA, perf sub, SN, 2-3/8" tubing to 6853'. Complete after P&A Wantz Granite Wash, recompleting Wantz Abo.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED RD Pitre TITLE Area Engineer DATE 6-6-83

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE JUN 13 1983

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUN 2 1983

LIBRARY