10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR 3393.6' 11. Check Appropriate Box to Indicate Nature of Notice, Reference Note, Reference No	WELL API NO. 30-025-26198 5. Indicate Type of Lease STATE FEE 6. State Oil & Gas Lease No. LG 1208
DISTRICTII PCO. Drawer DD, Anesia, NM 88210 Santa Fe, New Mexico 87504-2088 DISTRICT III 1000 NO Brazes Ad, Azec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL ON TO DEFERM OR PLUG BACK TO A DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS) 1. Type of Well: **** ON **** Onsear 2. Name of Operator Hunt Oil Company Onsear 3. Address of Operator Hunt Oil Company Onsear 3. Address of Operator Hunt Oil Company Onsear 4. Well Leater N :	 5. Indicate Type of Lease STATE FEE 6. State Oil & Gas Lease No.
IDDE Rid, Azze, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO PRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS) 1 Type of Well: ONE (PO NOT USE THIS FORM FOR PROPOSALS TO ORILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS) OTHER 2 Name of Operator Munt Oil Company 3. Address of Operator P. O. Box 1350, Midland, TX. 79702 4. Well Location Unit Letter	6. State Oil & Gas Lease No.
(DD NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOR. USE 'APULCATION FOR PERMIT' 1. Type of Well: GAS (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: 1. Type of Well: GAS (WALL CALL OR TO PROPOSALS.) 07182R 2. Name of Operator P. O. Box 1350, Midland, TX. 79702 4. Well Location Unit Letter N : 660 10. Letter N : 660 Section 23 Township 23-S Range 34-E 10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR 3393.6' 11. Check Appropriate Box to Indicate Nature of Notice, RC NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK PLUG AND ABANDON CASING TEST AND CE OTHER: 12. Describe Proposed of Completed Operations (Clearly state all pertinent datasis, and give pertinent datas, includ work) SEE RULE 1103. 1. Attempted to pull wireline plug & 5" permanent packer & 11,607' and 5" permaa 3. Ran 5" Mod "R" packer and tubing out of the well. <td< td=""><td>16 1208</td></td<>	16 1208
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOR. USE 'APULCATION FOR PERMIT' 1. Type of Well: 043 (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: 043 (Well Control 045 2. Name of Operator 045 Hunt 011 Company 3. 3. Address of Operator P. 0. Box 1350, Midland, TX. 79702 4. Well Location 1011 Letter N : 660 9. 0. Box 1350, Midland, TX. 79702 10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR 3393.6' 11. Check Appropriate Box to Indicate Nature of Notice, Re NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK CASING CASING TEST AND CE OTHER: 12. Describe Proposed or Completed Operations (Clearly state all periment datals, and give periment dates, includ work) SEE RULE 1103. 1. Attempted to pull wireline plug & 5" permanent packer & 13,100'; unsuc 2. Mill over and retreived 7-5/8" permanent packer & 11,607' and 5" perma 3. Ran 5" Mod "R" packer and tubing out of the well. 5. Set 5" permanent packer & 13,159'. Ran 2-7/8" production tubing in we 6. Frac Morrow perforations (originally perforated by Natomas during origin w/ 56,000 gailons 60 Quality Alcofoam w/ 29,000# sand. 7. Flow well to	
OME	7. Lease Name or Unit Agreement Name State "23" Com.
2. Name of Operator Hunt Oil Company 3. Address of Operator P. O. Box 1350, Midland, TX. 79702 4. Well Location Unit Letter N : 660 Feet From The South Line and 1980 Section 23 Township 23-S Range 34-E 10. Elevation (Show whether DF. RKB, RT. GR. etc.) GR 3393,6' 11. Check Appropriate Box to Indicate Nature of Notice, Re NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK PLUG AND ABANDON PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING CASING TEST AND CE DTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, includ work) SEE RULE 1103. 1. Attempted to pull wireline plug & 5" permanent packer & 13,100'; unsuc 2. Mill over and retreived 7-5/8" permanent packer & 11,607' and 5" perma 3. Ran 5" Mod "R" packer to isolate Morrow formation and ran 96 Hr bottom 4. Pulled Mod "R" packer and tubing out of the well. 5. Set 5" permanent packer & 13,159'. Ran 2-7/8" production tubing in we 6. Frac Morrow perforations (originally perforated by Natomas during origin w/ 56,000 gallons 60 Quality Alcoroam w/ 29,000# sand. 7. Flow well to clean-up and put on production. Theory certify that the information show is true and complete to the best of my trowledge and belict. SIGNATURE Operations 1 THE OR RRUT N	
3. Address of Operator P. O. Box 1350, Midland, TX. 79702 4. Well Location Unit Letter N Section 23 Township 23-S Range 34-E 10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR 3393.6* 11. Check Appropriate Box to Indicate Nature of Notice, RK NOTICE OF INTENTION TO: SUB ERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING CASING TEST AND CE OTHER: OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all persinent details, and give persinent dates, includ work) SEE RULE 1103. 1. Attempted to pull wireline plug & 5" permanent packer & 13,100'; unsuc 2. Mill over and retreived 7-5/8" permanent packer & 11,607' and 5" perma- 3. Ran 5" Mod "R" packer to isolate Morrow formation and ran 96 Hr bottom 4. Pulled Mod "R" packer and tubing out of the well. 5. Set 5" permanent packer & 13,159'. Ran 2-7/8" production tubing in we 6. Frac Morrow perforations (originally perforated by Natomas during origin w/ 56,000 gallons 60 Quality Alcofoam w/ 29,000\$ sand. 7. Flow well to clean-up and put on production. I hereby certify that the informat	8. Well No.
P. 0. Box 1350, Midland, TX. 79702 4. Well Location Unit Letter N:: 660 Feet From The South Line and 1980 Section 23 Township 23-S Range 34-E 11 10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR 3393.6' 11. Check Appropriate Box to Indicate Nature of Notice, Re NOTICE OF INTENTION TO: SUB ERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK EMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING ULL OR ALTER CASING CASING TEST AND CE OTHER: OTHER: 0 12. Describe Proposed or Completed Operations (Clearly state all pertiment datails, and give pertiment datas, includ work) SEE RULE 1103. 1. Attompted to pull wireline plug @ 5" permanent packer @ 13,100'; unsuc 2. Mill over and retreived 7-5/8" permanent packer @ 11,607' and 5" perma 3. Ran 5" Mod "R" packer to isolate Morrow formation and ran 96 Hr bottom 4. Pulled Mod "R" packer and tubing out of the well. 5. Set 5" permanent packer @ 13,159'. Ran 2-7/8" production tubing in we 6. Frac Morrow perforations (originally perforated by Natomas during origin w/ 56,000 gallons 60 Quality Alcofoam w/ 29,000\$ sand. 7. Flow well to clean-up and put on production. Threeby certif that the information above is tru	9. Pool name or Wildcat
Unit Letter N : 660 Feet From TheSouth	Antelope Ridge (Morrow)
Section 23 Township 23-S Range 34-E 10 10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR 3393.6' 11. Check Appropriate Box to Indicate Nature of Notice, RK NOTICE OF INTENTION TO: SUB ERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK CMADRARILY ABANDON CHANGE PLANS COMMENCE DRILLING ULL OR ALTER CASING CASING TEST AND CE OTHER: 12. Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, includ work) SEE RULE 1103. Attempted to pull wireline plug @ 5" permanent packer @ 13,100'; unsuc 2. Mill over and retreived 7-5/8" permanent packer @ 11,607' and 5" perma 3. Ran 5" Mod "R" packer to isolate Morrow formation and ran 96 Hr bottom 4. Pulled Mod "R" packer and tubing out of the well. 5. Set 5" permanent packer @ 13,159'. Ran 2-7/8" production tubing in we 6. Frac Morrow perforations (originaly perforated by Natomas during origin w/ 56,000 gallons 60 Quality Alcofoam w/ 29,000f sand. 7. Flow well to clean-up and put on production. Interdy certify that the information above is twe and complete to the best of my knowledge and belief. SIGNATURE Donald L. Yoder	·····
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR 3393.6' 11. Check Appropriate Box to Indicate Nature of Notice, Re NOTICE OF INTENTION TO: VERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING COMMENCE DRILLING CASING TEST AND CE OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, include work) SEE RULE 1103. 1. Attempted to pull wireline plug @ 5" permanent packer @ 13,100'; unsuc 2. Mill over and retreived 7-5/8" permanent packer @ 11,607' and 5" perma 3. Ran 5" Mod "R" packer to isolate Morrow formation and ran 96 Hr bottom 4. Pulled Mod "R" packer and tubing out of the well. 5. Set 5" permanent packer @ 13,159'. Ran 2-7/8" production tubing in we 6. Frac Morrow perforations (originally perforated by Natomas during origin w/ 56,000 gallons 60 Quality Alcofoam w/ 29,000f sand. 7. Flow well to clean-up and put on production. Three OF RENT NAME Donald L. Yoder	
NOTICE OF INTENTION TO: SUB: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK EMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING FULL OR ALTER CASING CASING TEST AND CE OTHER: FULL OR ALTER CASING OTHER: OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent datails, and give pertinent dates, includ work) SEE RULE 1103. OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent datails, and give pertinent dates, includ work) SEE RULE 1103. OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent datails, and give pertinent dates, includ work) SEE RULE 1103. Interview of Clearly state all pertinent datails, and give pertinent dates, includ work) SEE RULE 1103. 1. Attempted to pull wireline plug @ 5" permanent packer @ 13,100'; unsuc Interview of the state of the set o	MPM Lea County
NOTICE OF INTENTION TO: SUB: ERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK EMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING ULL OR ALTER CASING CASING TEST AND CE OTHER: ULL OR ALTER CASING OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent datails, and give pertinent dates, includ work) SEE RULE 1103. OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent datails, and give pertinent dates, includ work) SEE RULE 1103. OTHER: 13. Attempted to pull wireline plug @ 5" permanent packer @ 13,100'; unsuc . 2. Mill over and retreived 7-5/8" permanent packer @ 11,607' and 5" permaa 3. Ran 5" Mod "R" packer to isolate Morrow formation and ran 96 Hr bottom 4. Pulled Mod "R" packer and tubing out of the well. 5. Set 5" permanent packer @ 13,159'. Ran 2-7/8" production tubing in we 6. Frac Morrow perforations (originaly perforated by Natomas during origin w/ 56,000 gallons 60 Quality Alcofoam w/ 29,000f sand. 7. Flow well to clean-up and put on production. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE Donald L. Yoder TYPE OR FRIDT NAME Donald L. Yoder	port, or Other Data
EMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING ULL OR ALTER CASING CASING TEST AND CE THER: OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includ work) SEE RULE 1103. OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includ work) SEE RULE 1103. OTHER: 12. Attempted to pull wireline plug @ 5" permanent packer @ 13,100'; unsuc OTHER: 2. Mill over and retreived 7-5/8" permanent packer @ 11,607' and 5" perma 3. Ran 5" Mod "R" packer to isolate Morrow formation and ran 96 Hr bottom 4. Pulled Mod "R" packer and tubing out of the well. 5. Set 5" permanent packer @ 13,159'. Ran 2-7/8" production tubing in we 6. Frac Morrow perforations (originally perforated by Natomas during origin w/ 56,000 gallons 60 Quality Alcofoam w/ 29,000# sand. 7. Flow well to clean-up and put on production. Thereby certify that the information above is the and complete to the best of my knowledge and belief. SIGNATURE Denald L. Yoder TYPE OR FRUNT NAME Donald L. Yoder	SEQUENT REPORT OF
ULL OR ALTER CASING CASING TEST AND CE THER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all persinent details, and give persinent dates, includ work) SEE RULE 1103. OTHER: 12. Describe Proposed or Completed Operations (Clearly state all persinent details, and give persinent dates, includ work) SEE RULE 1103. OTHER: 12. Describe Proposed or Completed Operations (Clearly state all persinent details, and give persinent dates, includ work) SEE RULE 1103. OTHER: 12. Attempted to pull wireline plug @ 5" permanent packer @ 13,100'; unsuc Pulled 13,100'; unsuc 2. Mill over and retreived 7-5/8" permanent packer @ 11,607' and 5" perma 3. Ran 5" Mod "R" packer to isolate Morrow formation and ran 96 Hr bottom 4. Pulled Mod "R" packer and tubing out of the well. 5. Set 5" permanent packer @ 13,159'. Ran 2-7/8" production tubing in we 6. Frac Morrow perforations (originally perforated by Natomas during origin w/ 56,000 gallons 60 Quality Alcofoam w/ 29,000# sand. 7. Flow well to clean-up and put on production. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE Denald L. Yoder Child space for State Use) Otherations formation fo	X ALTERING CASING
THER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all periment details, and give pertiment dates, includ work) SEE RULE 1103. 1. Attempted to pull wireline plug @ 5" permanent packer @ 13,100'; unsuc 2. Mill over and retreived 7-5/8" permanent packer @ 11,607' and 5" perma 3. Ran 5" Mod "R" packer to isolate Morrow formation and ran 96 Hr bottom 4. Pulled Mod "R" packer and tubing out of the well. 5. Set 5" permanent packer @ 13,159'. Ran 2-7/8" production tubing in we 6. Frac Morrow perforations (originally perforated by Natomas during origin w/ 56,000 gallons 60 Quality Alcofoam w/ 29,000# sand. 7. Flow well to clean-up and put on production. 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE OEMall R. Gerlier TYPE OR PRINT NAME Donald L. Yoder	
DTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all periment details, and give pertinent dates, includ work) SEE RULE 1103. 1. Attempted to pull wireline plug @ 5" permanent packer @ 13,100'; unsuc 2. Mill over and retreived 7-5/8" permanent packer @ 11,607' and 5" perma 3. Ran 5" Mod "R" packer to isolate Morrow formation and ran 96 Hr bottom 4. Pulled Mod "R" packer and tubing out of the well. 5. Set 5" permanent packer @ 13,159'. Ran 2-7/8" production tubing in we 6. Frac Morrow perforations (originaly perforated by Natomas during origin w/ 56,000 gallons 60 Quality Alcofoam w/ 29,000# sand. 7. Flow well to clean-up and put on production. Ihereby certify that the information above is true and complete to the best of my knowledge and belief. SIONATURE Donald L. Yoder CTHER: OCNOMAL 2.361.	
 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includ work) SEE RULE 1103. 1. Attempted to pull wireline plug @ 5" permanent packer @ 13,100'; unsuc 2. Mill over and retreived 7-5/8" permanent packer @ 11,607' and 5" perma 3. Ran 5" Mod "R" packer to isolate Morrow formation and ran 96 Hr bottom 4. Pulled Mod "R" packer and tubing out of the well. 5. Set 5" permanent packer @ 13,159'. Ran 2-7/8" production tubing in we 6. Frac Morrow perforations (originally perforated by Natomas during origin w/ 56,000 gallons 60 Quality Alcofoam w/ 29,000\$ sand. 7. Flow well to clean-up and put on production. Threby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE	
 work) SEE RULE 1103. 1. Attempted to pull wireline plug @ 5" permanent packer @ 13,100'; unsuc 2. Mill over and retreived 7-5/8" permanent packer @ 11,607' and 5" perma 3. Ran 5" Mod "R" packer to isolate Morrow formation and ran 96 Hr bottom 4. Pulled Mod "R" packer and tubing out of the well. 5. Set 5" permanent packer @ 13,159'. Ran 2-7/8" production tubing in we 6. Frac Morrow perforations (originally perforated by Natomas during origin w/ 56,000 gallons 60 Quality Alcofoam w/ 29,000# sand. 7. Flow well to clean-up and put on production. Three Sr. Operations for the best of my knowledge and belief. SIONATURE	
 2. Mill over and retreived 7-5/8" permanent packer @ 11,607' and 5" perma 3. Ran 5" Mod "R" packer to isolate Morrow formation and ran 96 Hr bottom 4. Pulled Mod "R" packer and tubing out of the well. 5. Set 5" permanent packer @ 13,159'. Ran 2-7/8" production tubing in we 6. Frac Morrow perforations (originally perforated by Natomas during origin w/ 56,000 gallons 60 Quality Alcofoam w/ 29,000# sand. 7. Flow well to clean-up and put on production. 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE	
 3. Ran 5" Mod "R" packer to isolate Morrow formation and ran 96 Hr bottom 4. Pulled Mod "R" packer and tubing out of the well. 5. Set 5" permanent packer @ 13,159'. Ran 2-7/8" production tubing in we 6. Frac Morrow perforations (originally perforated by Natomas during origin w/ 56,000 gallons 60 Quality Alcofoam w/ 29,000# sand. 7. Flow well to clean-up and put on production. 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE Denald L. Yoder 	
 4. Pulled Mod "R" packer and tubing out of the well. 5. Set 5" permanent packer @ 13,159'. Ran 2-7/8" production tubing in we 6. Frac Morrow perforations (originally perforated by Natomas during origin w/ 56,000 gallons 60 Quality Alcofoam w/ 29,000# sand. 7. Flow well to clean-up and put on production. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE	ent packer @ 13,100'.
 5. Set 5" permanent packer @ 13,159'. Ran 2-7/8" production tubing in we 6. Frac Morrow perforations (originaly perforated by Natomas during origin w/ 56,000 gallons 60 Quality Alcofoam w/ 29,000# sand. 7. Flow well to clean-up and put on production. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE	hole pressure survey.
6. Frac Morrow perforations (originaly perforated by Natomas during origin w/ 56,000 gallons 60 Quality Alcofoam w/ 29,000≸ sand. 7. Flow well to clean-up and put on production. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE	
w/ 56,000 gallons 60 Quality Alcofoam w/ 29,000# sand. 7. Flow well to clean-up and put on production. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE Demails R. Goels TYPE OR PRINT NAME Donald L. Yoder (This space for State Use) Caroline Complete Use	1.
7. Flow well to clean-up and put on production. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE Donald R. Goelly TYPE OR PRINT NAME Donald L. Yoder (This space for State Use) OBIGINAL SUBJECT	al completion in May, 1979)
I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE OF PRINT NAME Donald L. Yoder (This space for State Use) ORIGINAL CLOSED	
TYPE OR PRINT NAME Donald L. Yoder (This space for State Use)	
(This space for State Use) CALORET CALORET	
(This space for State Use) ONGINAL DISET	ngineer DATE 7/27/94
 The second s	ngineer DATE 7/27/94 TELEPHONE NO.
APPROVED BY TITLE	TELEPHONE NO.
CONDITIONS OF APPROVAL, IF ANY:	
	TELEPHONE NO.
s k	TELEPHONE NO.