

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TR
(Other instructive
verse side)

CATE
on re

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Conoco Inc.	8. FARM OR LEASE NAME Meyer A-29
3. ADDRESS OF OPERATOR P.O. Box 460 - Hobbs, New Mexico 88240	9. WELL NO. 10
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FNL & 1980' FWL - Unit Letter C	10. FIELD AND POOL, OR WILDCAT Jalmat Yates Gas
14. PERMIT NO. 30-025-26419	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 29-22S-36E
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH Lea
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)

PULL OR ALTER CASING
MULTIPLE COMPLETE
ABANDON*
CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other)

REPAIRING WELL
ALTERING CASING
ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. MIRR.
2. Spot 25 sxs cement on top of cement retained at 3574'. Pull up to 3310' & circulate w/10 ppq mud.
3. Pull up to 2970' & spot 100' cement plug from 2970' - 2870'. Pull up to 1550' & spot 250' cement plug from 1550' - 1300'. Wait on cement for 12 hrs. Tag top of cement. If cement top is below 1300', fill with cement.
4. Perf 4 JSPPF at 1250'. POOH. Establish injection rate thru perfs and circulate up annulus w/10 ppq mud. If injection rate cannot be established, reperf 50' uphole until injection is accomplished. Pump 360 sxs class "C" cement w/18% salt to circulate up 5 1/2" x 8 1/8" annulus and fill 5 1/2" csq to surface. If cement does not circulate, pump 25 sxs cement.
5. Install P&A marker. For further information contact James Hedrick at 392-5869

18. I hereby certify that the foregoing is true and correct

SIGNED James D. Finney

TITLE Administrative Supervisor

DATE June 27, 1988

(This space for Federal or State office use)

APPROVED CHIEF, GENERAL RESOURCES

TITLE

DATE 7-18-88

CONDITIONS OF APPROVAL, IF ANY:

*See instructions on Reverse Side

This form is a legal document. It makes it a crime for any person knowingly and willfully to make to any department or agency of the Department of the Interior, false or fraudulent statements or representations as to any matter within its jurisdiction.

BLM-CO-26419(1) (2) (3) (4) (5) (6) (7) (8) (9) (10) (11) (12) (13) (14) (15) (16) (17) (18) (19) (20) (21) (22) (23) (24) (25) (26) (27) (28) (29) (30) (31) (32) (33) (34) (35) (36) (37) (38) (39) (40) (41) (42) (43) (44) (45) (46) (47) (48) (49) (50) (51) (52) (53) (54) (55) (56) (57) (58) (59) (60) (61) (62) (63) (64) (65) (66) (67) (68) (69) (70) (71) (72) (73) (74) (75) (76) (77) (78) (79) (80) (81) (82) (83) (84) (85) (86) (87) (88) (89) (90) (91) (92) (93) (94) (95) (96) (97) (98) (99) (100)