

DISTRIBUTION		
SANTA FE		
FILE		
U.S.O.B.		
LAND OFFICE		
OPERATOR		

P. O. BOX 7088
 SANTA FE, NEW MEXICO 87501

Revised 10-1-

5a. Indicate Type of Lease
 State ☒ Fee ☐
 5. State Oil & Gas Lease No.
 B-3480-1

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
 USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator

Gulf Oil Corporation

Address of Operator

P. O. Box 670, Hobbs, NM 88240

Location of well

UNIT LETTER B 430 FEET FROM THE North LINE AND 2310 FEET FROM
 THE East LINE, SECTION 16 TOWNSHIP 22S RANGE 37E NMPM.

7. Unit Agreement Name

8. Farm or Lease Name

R. E. Cole (NCT-A)

9. Well No.

21

10. Field and Pool, or Wildcat

Drinkard.

15. Elevation (Show whether DF, RT, GR, etc.)

12. County

Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
 NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☐
WELL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	
OTHER ☐		OTHER <u>Cleaned Out</u>	

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

POH with production equipment. Tag fill at 6610'. Clean out to 6669'.
 GIH with MA, perf nipple, SN and 2-3/8" tubing to 6646.52'. GIH with
 rods and pump; hang well on. Before clean out, 4 BO, 8 BW, 40 MCF; after
 clean out, 12 BO, trace water, 135 MCF. Complete after clean out 10-29-81.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED RDP ite TITLE Area Engineer DATE 11-5-81

PROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

NOV 5 1981