

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State ☐ Fee ☒

5. State Oil & Gas Lease No.  
LC 063387

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator BTA Oil Producers	8. Farm or Lease Name Bell Lake, 7909 JV-P
3. Address of Operator 104 South Pecos; Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER -F- , 1650 FEET FROM THE North LINE AND 2510 FEET FROM THE West LINE, SECTION 18 TOWNSHIP 23-S RANGE 34-E NMPM.	10. Field and Pool, or Wildcat Mid-Bell Lake - Serv.
15. Elevation (Show whether DF, RT, GR, etc.) 3,496' GL	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

### Proposed Procedure

1. Set 5" CIBP @ 12,900' w/2 sx cmt on top
2. 65 sx @ 11,445' to 11,335' (7-5/8" Liner top)
3. 65 sx @ 8,500' to 8,400' (T/Bone Springs)
4. 65 sx @ 5,000' to 4,900' (13-3/8" Shoe)
5. 65 sx @ 1,400' to 1,300' (Base Anhydrite)
6. 65 sx @ 700' to 600' (20" Shoe)
7. 15 sx @ Surface
8. Install Dry Hole Marker

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R. D. Boyce R. D. BOYCE TITLE Production Supervisor DATE 4/8/87

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT I SUPERVISOR

TITLE

DATE

APR 10 1987

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED  
APR 10 1967  
HOUSE OFFICE