

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-26766
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	V-3959
7. Lease Name or Unit Agreement Name	Quay AQU State
8. Well No.	1
9. Pool name or Wildcat	Und. North Bell Lake Wolfcamp
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3590.6' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South 4th St., Artesia, NM 88210	4. Well Location Unit Letter C : 660 Feet From The North Line and 1980 Feet From The West Line Section 10 Township 23S Range 33E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3590.6' GR	

II. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Continue re-entry ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-7-97 - Bled gas off. Circulate bottoms up. Displaced hole with 13# mud.
3-8-97 - Reverse circulated bottoms up. Pool Company switched pulling units out.
Rigged up pulling unit, swivel and reverse unit lines. Changed out BOP's.
3-9-97 - TOOH with bit. TIH with sealed bearing bit. Tagged CIBP at 11941'. Tried to drill for 2 hours - could not rotate.
3-10-97 - Worked on trying to drill for 4 hours. Swivel stalls out at 2300# torque. Does not matter if pumping or not. Tried setting weight down and then turning swivel - same results. TOOH with bit. TIH with 6" shoe dressed to 6-1/2" OD and heavy mesh on inside.
3-11-97 - Rigged up power swivel and stripper. Drilled on CIBP for 1-1/4 hours. Plug turned loose. Pushed CIBP to 11974'. Cut over a total of 4'. Can set 7 points on shoe and rotate with no torque. Assume rest of CIBP is spinning on top of liner. Circulated 4 hours.
3-12-97 - TOOH with shoe. Did not have CIBP in shoe. TIH with bit to CIBP on top of liner. Shut in for night.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Operations Technician DATE March 18, 1997
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1

(This space for State Use)

ORIGINAL SIGNED BY
GARY WINK
FIELD REP. II

MAR 20 1997

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: