Form 3160-5 (November 1983) (Formerly 9-331)		JE TED STATE		SUBMIT IN TR (Other instruct verse side)	CATE.	Form approved. Budget Bureau M Expires August 5. LEASE DESIGNATION	31, 1985	
(1 0		J OF LAND MANA		RECEIVED		NM-11967		
SUN	IDRY NOTI	CES AND REP				6. IF INDIAN, ALLOTTEE	OR TRIBE NAME	
	form for propos-	TION FOR PERMIT	n or plug back t	o a different reservoir	r. }	7. UNIT AGREEMENT NA	ME	
WELL WELL	X OTHER			<u>, çı</u>		0		
			A HE Alexandra A ER	S	8. FARM OR LEASE NAM	t		
STRATA PRODUCTION COMPANY						CUERVO FEDERAL 9. WBLL NO.		
3. ADDRESS OF OPERATOR								
<ul> <li>648 PETROLEUM BUILDING, ROSWELL, NM 88201</li> <li>4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface</li> </ul>					• •	10. FIELD AND FOOL, OR WILDCAT DEMONSTRATE		
1980' FSL & 1980' FEL						11. SEC., T., B., M., OR BLK. AND SURVEY OR AREA		
unit J						Section 14, T23S, R32E		
14. PERMIT NO.	<i>U</i>	15. ELEVATIONS (Show	whether DF, RT, C	R, etc.)		12. COUNTY OR PARISH	18. STATE	
		3705' (	3L			LEA	NM	
16.	Check Ap	propriate Box To Ir	ndicate Natur	e of Notice, Repo	ort, or O	ther Data		
	NOTICE OF INTEN	TION TO :			នប <b>ននាះឲ្</b> បា	INT REPORT OF :		
TEST WATER SHUT-	)F.F.	ULL OR ALTER CASING		WATER SHUT-OFF		BEPAIRING W	ELL	
FRACTURE TREAT		IULTIPLE COMPLETE		FRACTUBE TREATME	NT	ALTERING CA	SING	
SHOOT OR ACIDIZE	A	BANDON*		SHOOTING OR ACIDIZ	LING	ABANDONMEN	<b>T</b> •	
REPAIR WELL	c	HANGE PLANS		(Other)	t romite	of multiple completion		
	her)Complete as SWD-433 (Norg : Report results of multiple completion on Well Completion or Recompletion Report and Log form.) RIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any							
17. DESCRIBE PROPOSED ( proposed work, I nent to this work.)	f well is directio	NATIONS (Clearly state : nally drilled, give subs	all pertinent det urface lo <mark>cati</mark> ons	ails, and give pertine and measured and tru	nt dates, f pe vertical	including estimated date depths for all markers	e of starting any and gones perti-	
In accordance	with the	New Mexico Oil	l Conserva	tion Division	, Admi	nistrative Ord	ler #SWD-433.	

Strata Production plans to convert the Cuervo Federal #1 Well to a Salt Water Disposal system in the following manner:

- 1. Rig-up & perf squeeze holes at 6150' and 5350'. Set retainer at 6125'(+/-).
- 2. Break circulation& use sufficient cement to cover zone 6150' to 5350'.
- 3. TOH w/ tubing; set for 24 hours. TIH w/ bit & tools, drill out cement.
- 4. Shut-in BOP to test csg & squeeze to 1250#, leave for 15 minutes.
- 5. TOH w/ tools. TIH & perf 5998'-87', 5871'-58', 5686'-71', 5598'-92' and 5520'-5499'. Acidize & prep to inject in same.
- 6. TIH w/ zinc coated pkr & plastic coated 2 7/8" tbg. Flange up head & build battery for injection.
- NOTE: Will notify the supervisor of the Hobbs district office of the failure of tubing, casing or packer.

18. I hereby certify that the foregoing is true and correct SIGNED	TITLE Vice President	DATE 07/25/91
(This space for Federal or State office the) APPROVED BY CONDITIONS OF APPROVAL, IF ANY :	TITLE	DATE

## \*See Instructions on Reverse Side