ENERGY AND MINERALS DEPARTMENT						
JIL CONSERVATION DIVISIO				Form C-103		
DISTRIBUTION P. D. BOX 2088 SANTA FE SANTA FE, NEW MEXICO 87501				Revised 19-1-78		
TILE				Sa. Indicate Type	olLease	
U.S.O.S.				State XX	F++	·
DERATOR				5. State Oil & Ga L-13838	la Lease No.	
					mmm	\overline{Z}
SUNDRY NOTICES AND REPORTS ON WELLS 100 NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DECEMENT OF PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)						
1. •IL . •IL . •I				7, Unit Agreemer 8, Form of Lease		
2. Name of Operator				CURRY STATE		
ESTORIL PRODUCING CORPORAT	<u>10N</u>		<u></u>	9. Well No.		_
1100 Vaughn Building, Midl	and, Tex	as 79701		1		
4, Location of Weli				10. Field and Pa	RIDGE (MORI	201
UNIT LETTERA660 FEET FROM THE NLINE AND660 FEET FROM				ANTELOPE		
THE LINE, SECTION 22 TOWN	18HIP23-	S RANGE	<u>34-E</u> NMPM	·AIIIIIIII		Ŋ.
TTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTT	(Show whether	DF, RT, GR, eic.)	12. County	<u>MIIIIIX</u>	Z
;; }}]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]	410 GL			LEA		7
The Check Appropriate Box To NOTICE OF INTENTION TO:	o Indicate N	ature of Noti 		her Data T REPORT OF:	:	
	. ABANDON	REMEDIAL WORK		ALTE		7
		COMMENCE DRILL	.1+6 0945.		AND ABANDONMENT	ปี
PULL OR ALTER CASHS CHANGE	PLANS	CASING TEST AND				
			OGRESS REPO ERATIONS	RI OF COMP		
отися		l	· · · · · · · · · · · · · · · · · · ·	antimated data of		
17. Describe Proposed or Completed Operations (Clearly state a work) SEE RULE 1 103. PROGRESS REPOR	T OF COM	PLETION O	PERATIONS			•••
The casing head and tubing heads we stack in place. The hole was clear section 13,099' to 13,205'.	were nip ned up t	pled up w o total d	ith a doubl epth to tes	e blow out t the oper	prevente hole Mori	: :ow
2-11-81						
The 14 hour SITP was 1900 psi, blo & blew fluids from hole to 13,148 open hole section. After recoveria 2-21-81	'. Spott	ed 1000 g	allons 7-1/	2% acid &	il tubing pumped int	:0
rigged up wire line & ran an open	hole st	ring shot	& shot acr	oss Morrow	sand body	
Cleaned out hole & spotted 500 ga with 6000 gal 7-1/2% acid. Maximu Cleaned up load & found open hole could not clean up open hole sect:	llons ac m pressu sloughi	id in ope re 9000 p	n hole sect si. Rate 7.	ion, then 7 BPM. SID	acidized P 5900 ps:	
4-1-81						
Set a 5-1/2" OD Baker cast iron b plug. New PBTD 13,036'.	ridge pl	ug at 13,	050'. Cappe	d with 14'	cement	
Set Brown Oil Tools BD-l packer a	t 12,790	'. Tested	tubing to	6000 psi,	ok.	
18. I hereby certify that the information above is true and compl	ste to the best	of my knowledge a	and belief. CONTI	NUED ON AT	TACHED SHI	CET
Driel Miller	TITLE	Igent for	Estorif	DATE_C	-15-81	
Orig. Signsid		V		-		
Jerry Semini	TITLE			DATE	<u>UN 24 198</u>	1
CONDITIONS OF APPROVAL, IF ANYI						

Rigged up wire line and perforated through tubing with 1 shot at each depth 12,985, 87, 89, 94, 99, 13,001, 03, 07, and 09', all in the Morrow formation. Well had 550 psi on tubing after perforating, opened to pits and well continued to unload. Flowing about 100 MCFPD. Acidized perfs (Morrow) 12,985' to 13,009' with 6000 psi. Well did not flow after treatment.

Rigged up wire line and perforated Morrow sands shot at each depth: 12,824, 825, 826, 827, 828, 829, 844, 848, 850, 851, and 852. Blew well dry with nitrogen. Acidized perfs with 6000 gallons 7-1/2% acid. Blew well down and cleaned to pits. Had only slight blow of gas, non-commercial rate.

Plugged back Morrow formation as follows: Set bridge plug at 12,806' and capped with 35' of cement.

> Gray Signal In Jerry Series