

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well
 Oil Well Gas Well Other

2. Name of Operator
CITATION OIL & GAS CORP.

3a. Address
P.O. Box 690688, Houston, Texas 77269-0688

3b. Phone No. (include area code)
(281) 517-7800

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
Unit H; 1980' FNL & 660' FEL; Sec. 28, T23S, R34E

5. Lease Serial No.
LC 067715

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.
CA 891008492C

8. Well Name and No.
Antelope Ridge Unit #8

9. API Well No.
30-025-26868

10. Field and Pool, or Exploratory Area
Antelope Ridge Atoka

11. County or Parish, State
Lea County, New Mexico

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other _____
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operations (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

On 3/27/00, MIRU. Blew down tubing and casing to plant. Pumped 25 bbls 2% KCl down tubing; pumped 120 bbls 2% KCl with 55 gals R-2264 down casing. Acidized Atoka 12,386' - 12,410' with 2400 gals 20% MSR acid foamed to 50Q with CO2. Flowed well to test tank for 5 hours and recovered 24 BLW. Opened well to plant. Well producing @7 AMjwith 100# FTP to battery on 3/28/00. As of 4/3/00 producing 782 Mcf on gas lift with 222 bbls fluid.

(ORIG. SGD.) GARY GOURLEY

14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed) Debra Harris	Title Regulatory Analyst
Signature <i>Debra Harris</i>	Date 4/7/00

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by	Title	Date
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

5 GWW

RECEIVED
APR 10 2000
BLM
ROSWELL, NM