

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on re-
verse side)

Budget Bureau No. 1004-1
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

LC 071949

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

ANTELOPE RIDGE UNIT

8. FARM OR LEASE NAME

ANTELOPE RIDGE

9. WELL NO.

7

10. FIELD AND POOL, OR WILDCAT

ANTELOPE RIDGE ATOKA

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

SW/4 NE/4 SEC. 27

T23S-R34E

12. COUNTY OR PARISH

LEA

13. STATE

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

SHELL WESTERN E&P INC.

3. ADDRESS OF OPERATOR

P. O. BOX 576, HOUSTON, TEXAS 77001 (WCK 4435)

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1650' FNL & 1980' FEL SEC. 27

14. ~~XXXXXX~~ API NO.

30-025-26668

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3471' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) RAN BHP BOMBS/4-PT TEST

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

10-01-86: Started flowing well thru 32/64" choke.

10-09-86: Ran dual BHP bombs & set in "F" nipple @ 11,386'. Set blanking plug in "F" Nipple @ 11,317'.

10-17-86: Pulled blanking plug & BHP bombs. Ran BHP bomb w/24 hr clock. Ran 4-pt test, flowing each rate for 1 hr. Pulled BHP bomb. SI well.

11-05-86: Returned well to production.

18. I hereby certify that the foregoing is true and correct

SIGNED

A. J. Fore

A. J. FORE

TITLE SUPERVISOR REG. & PERMITS

DATE NOVEMBER 12, 1986

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

RECEIVED
NOV 17 1986
U.S.S.
HOBBS OFFICE