Submit 3 Copies to Appropriate District Office	State of New Mexico Energ, dinerals and Natural Resources Department		irces Department	Form C-103 Revised 1-1-89		
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL, CONSERVATION DIVISION P.O. Box 2088		DIVISION	WELL API NO.		
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico 87504-2088			30-025-27136 5. Indicate Type of Lease STATE STATE FEE		
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410				6. State Oil & Gas Lease No. V-1811		
	ICER AND REPORTS ON	WELLS				
SUNDRY NOTICES AND REPORTS ON WELLS ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				7. Lease Name or Unit Agreement Name		
1. Type of Well: OIL OIL WELL	OTHER			State "IG"		
WELL WELL WELL	1			8. Well No.		
Harvard Petroleum Cor	noration			1		
3. Address of Operator				9. Pool name or Wildcat		
P.O. Box 936, Roswell 4. Well Location				West Triste Draw - Delaware		
Unit Letter <u>B</u> : <u>660</u> Feet From The <u>North</u> Line and <u>1980</u> Feet From The <u>East</u> Line						
Section 32 Township 23S Range 32E NMPM Lea County   10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3664' GR GR MPM Lea County						
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data						
NOTICE OF IN	ITENTION TO:		SUB	SEQUENT REPORT OF:		
	PLUG AND ABANDON		REMEDIAL WORK			
	CHANGE PLANS		COMMENCE DRILLING			
OTHER:			OTHER: Deviate & Sidetrack			
12. Describe Proposed or Completed Ope work) SEE RULE 1103.	erations (Clearly state all pertinent de	etails, and	give pertinent dates, inclu	iding estimated date of starting any proposed		
11/25 += 12/10/07 Sidetra	craper, $11/18/97$ Set CIBP at ck and drill to 8616' w/ 6 $\frac{1}{2}$ " h d N80 csg to 8615', cmt w/ 74	40 sx Su	iper "C" Modified	whipstock & mill window in csg. & 248.9' east of surface location.		

- 12/16/97 Run CET, found cmt top at 6500', perf 4 sqz holes at 6400
- 12/18/97 Sqz w/ 465 sx Super "C" modified

I

- 12/22/97 Drill out and test to 3000 psi, held good.
- 12/24/97 Run CBL, TOC at 2500', perf 8482-86' and 8430-34' (10 holes), acidize w/ 1000 gal 10% HCL, Frac w/ 21,400 gals 50 Q CO2 foam w/ 35,000# 20/40 Ottowa, tailed w/ resin coated sand. Swab test zone.
- 1/20/98 Set RBP at 8328', perf 7385-95' w/ 20 holes, Acidize w/ 1000 gals 10% HCL. Frac w/ 13,300 gals 50 Q CO2 foam w/ 17,500# 20/40, tail w/ 9840# 20/40 resin coated sand. Swab test zone.
- 1/27/98 Pull RBP, swab test both zones then SI, waiting on gas line.
- 2/21/98 Hook up well, begin producing w/ hydraulic jet pump. IP 80 BO, 78 MCF, 237 wtr in 24 hr period.

I hereby certify that the information above is true and complete to the best of my loss SKINATURE	mgVice_President	DATE <u>4-8-98</u> (505) TELEPHONE NO <sub>6</sub> 23-1581
(This space for State Use) (This space for State Use)		1904 S & 1994
GARY WINK APPROVED BY FIELD FIELD FIELD FIELD	mue	DATE

V .