

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Arco Oil and Gas Company Division of Atlantic Richfield Company		8. Farm or Lease Name Shipley "A" WN
3. Address of Operator P.O. Box 1710, Hobbs, New Mexico 88240		9. Well No. 6
4. Location of Well UNIT LETTER E 1650 FEET FROM THE North LINE AND 660 FEET FROM THE West LINE, SECTION 27 TOWNSHIP 22S RANGE 36E NMPM.		10. Field and Pool, or Wildcat 7P Gas Jalmat Yates Tansil Yates
15. Elevation (Show whether DF, RT, GR, etc.) 3499.1' GR		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- MIRU, POH w/pump & rods. ND WH. NU BOP. Tag PBTD @ 3494'.
 - POH.
 - GIH w/tbg OE to 3480' & spot cmt w/TOC @ 3390'. Tag TOC w/tbg.
 - RIH w/CA.
- Return to production in same zone after plugging off perfs 3390' to 3494'.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Steven D. Smith TITLE Dist. Prod. Supt. DATE 10/28/85

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

OCT 28 1985

O.C.P.
HOBBS OFFICE