



STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT
OIL CONSERVATION DIVISION
HOBBS DISTRICT OFFICE

GARREY CARRUTHERS
GOVERNOR

October 17, 1989

POST OFFICE BOX 1980
HOBBS, NEW MEXICO 88241-1980
(505) 393-6161

Grace Petroleum Corp.
Attn: William P. Baswell
6501 North Broadway
Oklahoma City, OK 73116

Re: P&A Procedure
Grizzell Deep #1-P
Section 5, T22S, R37E

Gentlemen:

We are returning your intention to P&A the above-referenced well. The P&A procedure approved March 3, 1988, is still in effect and since the casing is collapsed in this well the procedure may vary from what is approved.

A copy of the procedure approved March 3, 1988, is attached for your records.

Very truly yours,

OIL CONSERVATION DIVISION

Jerry Sexton
Supervisor, District I

ed

Encl.

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

C - CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

SUNDRY NOTICES AND F
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO C
USE "APPLICATION FOR PERMIT -" (FORM

1. OIL WELL ☒ GAS WELL ☐ OTHER-
2. Name of Operator
Grace Petroleum Corporation Attentic
3. Address of Operator
6501 N. Broadway, Oklahoma City, Oklah
4. Location of Well
UNIT LETTER P 330 FEET FROM THE
THE East LINE, SECTION 5 TOWNSHIP

15. Elevation (Shc
3423.2',

16. Check Appropriate Box To Ind
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐
PLUG AND ABANDON ☒
CHANGE PLANS ☐
OTHER ☐

Notice, Report or Other Data
SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) *SEE RULE 1103.

1. Kill well.
2. POOH w/tbg.
3. Set 35' of cement on top of retainer at 7210' (wireline).
4. RIH w/tbg.
5. Spot 25 sacks of cement from 7150' to 7050'.
6. Circulate hole w/10 ppg brine + 25 lbs/bbl of salt gel.
7. Spot 25 sacks of cement from 6200 to 6300'.
8. Spot 25 sacks of cement from 3300 to 3400'.
9. POOH w/tbg. RU WL & perf 1300-1302. RD WL & RIH w/tbg.
10. Spot 39 sacks of cement from 1100-1300' (inside & outside 5-1/2" csg).
11. POOH w/tbg. Perf 350-352'. RIH w/tbg.
12. Spot 28 sacks of cement from 350-250' (inside & outside of 5-1/2" csg).
13. Spot 10 sacks of cement from 0-10'. Cut off WH 4' below GL.
14. Weld on plate & ID (Operator, lease, section, township, range, distance from section lines).

* Give Oil Conservation Division 24 hours notice before P&A begins.

5. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED William P. Baswell
William P. Baswell

TITLE Operations Engineer

DATE 10/10/89

APPROVED BY _____

TITLE _____

DATE _____

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

OCT 16 1989

OCD
HOBBS OFFICE



OIL CONSERVATION DIVISION
RECEIVED

'89 OCT 13 AM 9 09

Grace Petroleum Corporation
Subsidiary of W. R. Grace & Co.

Broadway Executive Park
6501 North Broadway
Oklahoma City, Oklahoma 73116-8298
Phone (405) 840-6600
FAX—(405) 840-6887

October 10, 1989

State of New Mexico
Energy and Minerals Department
Oil Conservation Division
P. O. Box 2088
Santa Fe, New Mexico 87501

Re: Intent P&A Sundry
Grizzell Deep #1
Lea County, New Mexico

Gentlemen:

Attached for your review and approval is an Intent Sundry Notice to plug and abandon the above referenced well. Once approved and completed, the location will be restored per the landowner and State rules and regulations.

Please advise the undersigned if any questions arise. Thank you.

Very truly yours,

William P. Baswell
Operations Engineer

cc: G. H. Britsch
W/F