

GEOLOGICAL SURVEY HOBBS, NEW MEXICO 88240 NM-25465

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR SANDERS PETROLEUM CORPORATION		8. FARM OR LEASE NAME Williamson Federal
3. ADDRESS OF OPERATOR 11000-D Spain Rd. N.E., Albuquerque, N.M. 87111		9. WELL NO. #1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FEL & 1650' FSL		10. FIELD AND POOL, OR WILDCAT Wildcat
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 25, T23S, R33E
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3632 GL	12. COUNTY OR PARISH Lea
		13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT

REPAIR WELL

CHANGE PLANS

(Other) Report

For Prod.

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work).*

Performed the following work 9-10-81 thru 10-10-81:

Perforated 5337' - 5349' w/ 2 jspf, swabbed 15 bbls salt water per hour (191,000 chlorides) w/ trace oil, show of gas. Set CIBP at 5328; dumped 15' cement, PBTD 5313'.

Perforated 5275' - 5289' w/ 2 jspf, swabbed 10 bbls. salt water per hour (193,000 chlorides) w/ trace of oil, fair show of gas. Set CIBP at 5265', dumped 15' cement, PBTB 5250'.

Perforated 5214' - 5222' w/ 2 jspf, swabbed 20 bbls salt water per hour (187,000 chlorides) w/ trace of gas, diminishing to no show.

Will prepare procedure to P & A.

RECEIVED

FEB 14 1983

**OIL & GAS
MINERALS MGMT. SERVICE
ROSWELL, NEW MEXICO**

18. I hereby certify that the foregoing is true and correct

SIGNED

Patti Stewart

TITLE Agent

DATE February 10, 1983

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR RECORD

RMB
JUL 5 1983

***See Instructions on Reverse Side**

ROSWELL, NEW MEXICO

RECEIVED

JUL 7 1983

O.C.D.
HOBBS OFFICE