STATE OF NEW MEXICO	
ENERGY AND MINERALS DEPARTMENT	
OIL CONSERVATION DIVISION	
DISTRIBUTION P. O. BOX 2088	Form C-103
SANTA FE, NEW MEXICO 87501	Revised 10-1-75
FILZ	Su. Indicate Type of Lease
LAND OFFICE	State X Fue
OPENATOR	5. State Off & Gus Leans No.
have an and the second se	LG-1025
SUNDRY NOTICES AND DEDODTS OF WELL	
SUNDRY NOTICES AND REPORTS ON WELLS 100 NOT USE THIS FORM FOR HEADASALS TO DAILL ON TO DEFPEN OF PLUS ALCH TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT _" (FORM C-1011 FOR SUCH PHOPOSALS.)	
OIL CAS X DTHER-	7. Unit Agreement Name
	8. Farm or Lease Nume
<u>Amoco Production Company</u>	State ME Com
3. Address of Cperator	9, Well No.
P. O. Box 68, Hobbs, New Mexico 88240	1Y .
4. Location of Well UNIT LETTER N 660 FEET FROM THE South 2030 FEET FR	Antelope Ridge Atoka
THE West LINE, SECTION 11 23-S 34-E NM	
(1) (1) (1) (1) (1) (1) (1) (1) (1) (1)	12. County
3363.9' GR	Lea
Check Appropriate Box To Indicate Nature of Notice, Report or ( NOTICE OF INTENTION TO: SUBSEQUE	Other Data INT REPORT OF:
PERPORM PEMEDIAL WORK	ALTERING CASING
COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	
07HER	· 🗂
OTHER	L
17. Describe Processed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includ work) SEE RULE 1103.	ing estimated date of starting any proposed
Perfed Atoka interval 12255'-12378' with 2 SPF using 3" gun. Perfed Atoka interval 12255'-12378' with 2 SPF using 3" gun. Perfed 2 days and Ran BHP bombs 1-23-4 in Atoka tubing. POH with BHP bombs, BHP was 5108 psi, static. equipment. Ran blanking plug at 13033'. Perfed 12116'-1213' with trievamatic packer, and tubing. RBP set at 12230', packer set a 6000 psi. Released packer, pulled tubing and set pkr. of 11784. Rafraced 12072'-12198' with 10000 gals x-linked 40# gel and 5000 gals gel with 1.5# per gal interprop and 2000 gals CO2. Pumped off after 2814 gals gel and 1400 gals CO2. Ran post GR/Temp sum on 48/64", 650 PSI. Flow tested and recovered apx 150 BLW. Ran tubing to 12230'. Circulated bottoms up and no gas. Released a Ran on-off tool, tubing, and packer. Well began to flow, circulatched onto packer at 12961'. Ran latch assembly, profile nipp onto dual packer at 11162'. Ran DPSI plug, set at 11180'.	84, set bombs at 11171' POH with dual production ith 4 SPF. Ran RBP, re- at 12220'. Tested RBP to an GR/Temp survey and gals CO2. Pumped 4000 2#/gal sand and screened rvey. Opened to pit n retrieving head and and pulled RBP and tubing. lated 2 hrs and well died. ole, and tubing. Latched

to 800 PSI and set packer. Ran RBP pulling tool and pulled up equalizing prong. Ran 2" RB, probe, and pulled up plug. Set plug in coupling and removed BOP and installed tree. Tested tree to 1000 psi tested OK. Pressured up casing to 1000 psi, OK. Ran 2" pull-ing tool and attempted to pull up equalizing prong, tagged fill at 12984'. Ran bailer O+5-NMOCD,H 1-J. R. Barnett, HOU Rm. 21.156 1-F. J. Nash, HOU Rm. 4.206 1-GCC .s. I hereby certily that the information above is true and complete to the best of my knowledge and belief. Assist. Admin. Analyst 7-27-84 DATE CENSINAL SECRED BY SEREY MERTON JUL 27 198

DISTRICT 1 : FRENDISOR

DITIONS OF APPROVAL, IF ANY

to 12984 and POH. Swabbed Atoka 18 hrs. Rec apx 180 BLW and burnedaurs'flare while swabbing. Perfed 13019'-20' with 4 SPF in tubing. Currently flow testing Morrow.

NECENVED JUL 27 1984 MODEL CARCE

1

.