

United States Department of Interior
Bureau of Land Management

DISTRICT: Roswell. Hobbs Office (CRH)

RECEIVED

INSPECTION RECORD - ABANDONMENT MAR 27 11 03 AM '89

WELL NO. TRISTO DRAW Fed: Gulf #01 OPERATOR LEADY OIL COMPANY
 & SESW SEC. 11 T 235R 32E LEASE NO. NM 19620
 FIELD AREA N/cat TYPE OF WELL POW
 COUNTY: LEA CONTRACTOR MAYO MARRS Csg. Pullers
 STATE: NEW MEXICO INC ISSUED NO

* DRY HOLE, DEPLETED PRODUCER, SERVICE, WATER WELL, ETC.

MECHANICAL PLUG PLACEMENT DATE 3-13-89 Set CIRP@ 9280

Shot casing OFF@ 3500

CEMENT PLUG SPOTTING METHOD: BALANCE ✓ 2 PLUG BAILER

ADDITIONAL REMARKS Tried To cut at csg. Shoe - pumped 1000' on third hole
well - had to shoot off at 3500

PLUG #1	<u>9280</u> TO <u>9245</u>	WITH <u>7</u> SACKS	TAG OR TEST	<u>Tag</u>
PLUG #2	<u>7000</u> TO <u>6850</u>	WITH <u>70</u> SACKS	TAG OR TEST	<u>—</u>
PLUG #3	<u>3550</u> TO <u>3221</u>	WITH <u>80</u> SACKS	TAG OR TEST	<u>Tag</u>
PLUG #4	<u>650</u> TO <u>500</u>	WITH <u>50</u> SACKS	TAG OR TEST	<u>—</u>
PLUG #5	<u>50</u> TO <u>00</u>	WITH <u>30</u> SACKS	TAG OR TEST	<u>To Surface</u>
PLUG #6	<u> </u> TO <u> </u>	WITH <u> </u> SACKS	TAG OR TEST	<u> </u>
PLUG #7	<u> </u> TO <u> </u>	WITH <u> </u> SACKS	TAG OR TEST	<u> </u>

DATES (s) 3-13-89 & 3-17-89, + INSPECTOR Jack Johnson
 TOTAL TIME ON JOB 16 HRS. INCLUDES 4 HRS. TRAVEL 2 OVERTIME

	YES	NO	NA	ENF
Plugs spotted across perforations if casing set? ..	X			S
Plug spotted at any casing stub?	X			S
Open hole plugs spotted as specified?			X	S
Mechanical plugs set as specified?	X			S
Cement quantities as specified?	X			S
Plugs tested as specified?	X			S
Pipe withdrawal rate satisfactory? .. PA. Dept. 12/17/90	X			W