

November 1983)
formerly 9-331)

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
NEW MEXICO 88240

EXPIRES August 31, 1985
LEASE DERIVATION AND SERIAL NO.
NM-19620

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
2. NAME OF OPERATOR Happy Happy Oil Company	7. UNIT AGREEMENT NAME
3. ADDRESS OF OPERATOR P.O. Box 343, Artesia, N.M. 88210	8. FARM OR LEASE NAME Triste Draw Fed.
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface Unit N,660' from the SL, and 1980' from the WL, Section 11, Township 23S, Range 32E N.M.P.M.	9. WELL NO. #1
14. PERMIT NO.	10. FIELD AND POOL, OR WILDCAT Diamondtail bn Spring
15. ELEVATIONS (Show whether SP, ST, OR, etc.) 3728 GR	11. SEC., T., R., M., OR BLM, AND SURVEY OR AREA Sect: 11 T23S, R32E
	12. COUNTY OR PARISH Lea
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

Re-Entry BLM Approved 10-31-86 (NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all members and zones pertinent to this work.)

10-31-86 MOVE IN AND RIG UP BABER WELL SERVICE #76. CLEAN OUT CELLAR AND CUT OFF DRY HOLE MARKER. DIG OUT BOTTOM OF CELLAR DEEPER. PEEL OFF 16" CSG. AND INSTALL 10-3/4" HEAD. PICKUP BHA AND CLEAN-OUT TO TOP OF 7-5/8 CSG. TOP OF CSG. @ 10' FROM SURFACE NOTIFIED BLM OF SPUD AT 2:30 P.M. 10-31-86 PICK UP 7-5/8 SPEAR AND LATCH INTO 7-5/8 CSG. UNABLE TO PULL 7-5/8 CSG. UP INTO 10-3/4 HEAD. SIFN.

11-1-86 RIG UP CSG. JACKS AND TRY TO PULL 7-5/8 UP INTO 10-3/4 WELL HEAD. CUTOFF 10-3/4 WELL HEAD AND DIG CELLAR DEEPER. STILL UNABLE TO PULL CSG. UP INTO WELL HEAD. SET IN REVERSE UNIT AND EQUIP. FILL REVERSE PIT WITH WATER. SIFN.

11-2-86 USE JACK HAMMER TO DIG CELLAR DEEPER WELD ON 10-3/4 WELL HEAD LOWER. USE CSG. JACK AND PULL 7-5/8 CSG. THROUGH 10-3/4 WELL HEAD. SET SLIPS W/370,000# PACKOFF WELLHEAD. BRING SURFACE VALVE TO SURFACE. ADD 7-5/8 CSG. TO BRING UP TO GROUND LEVEL WELD ON 7-5/8 NIPPLE UP ON 7-5/8 CSG. SIFN.

11-3-86 PICK UP 4-3/4 COLLARS AND 6-1/4 BIT. DRILL DOWN TOP CEMENT PLUG. FELL THRU AT 190' UNLOAD TBG ON RACKS. SIFN. PROGRESS 190' TD 190'

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

DATE

(This space for Federal or State office use)

ACCEPTED FOR RECORD

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

DEC 09 1986

*See Instructions on Reverse Side

CARLSBAD, NEW MEXICO