

November 1983
formerly 9-331

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

EXPIRATION DATE: 1004-0135
Expires August 31, 1985

LEASE DESIGNATION AND SERIAL NO.

NM-19620

IF INDIAN, ALLOTTEE OR TRIBE NAME

UNIT AGREEMENT NAME

FARM OR LEASE NAME

Triste Draw Fed.

WELL NO.

#1

FIELD AND POOL, OR WILDCAT

Diamondtail bn Spring

SUC. T. B. N. OR B.L. AND
SURVEY OR AREA

Sect: 11 T23S, R32E

12. COUNTY OR PARISH 13. STATE

Lea

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Happy Happy Oil Company

3. ADDRESS OF OPERATOR

P.O. Box 343, Artesia, N.M. 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

Unit N, 660' from the SL, and 1980' from the WL,

Section 11, Township 23S, Range 32E N.M.P.M.

14. PERMIT NO.

15. ELEVATIONS (Show whether SF, ST, OR, etc.)

3728 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREATMENT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

Re-Entry BLM Approved 10-31-86

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent data, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all mothers and zones pertinent to this work.)

11-12-86 TBG -0 CSG-0

Set lok-set plug @ 11800'. Pull up and set PKR @ 11320'. Rig up swab and start to swab. Beginning fluid level 200'. Final fluid level @ 6800. Swab 50 bbls to tank, tbg very rough. Final swab run showing small show of gas. SIFN. Swabbing old perfs 11401-11751 Still open.

11-13-86 TBG - 300# CSG - 0

Open up and bleed down to 0 in 15 min. Beginning fluid level -4000'. First swab run had small amount of oil on top. Swab 75 bbls water to tank. Swab down to SN. Wait 1 hr. between runs and had about 500' fluid entry. Beginning to cut 5% oil on last 2 runs. SIFN

11-14-86 TBG. 225 CSG -0

Bleed tbg to 0 in 10 min. Rig up to swab. Beginning fluid level @ 7800' First run approx. 1-1/2 bbls oil. Start swabbing water with good show of gas. Swab down to SN. Approx. 300-400'/hr fluid entry. Cut approx. 10-15% oil Shut in for the weekend.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

DATE

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

DEC 09 1986

*See Instructions on Reverse Side