

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. NM19620	
2. NAME OF OPERATOR Upland Production Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P.O. Box 481, Midland, Tx. 79702		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FSL & 1980' FWL		8. FARM OR LEASE NAME Triste Draw Federal	
14. PERMIT NO.		9. WELL NO. 1	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3728' GL		10. FIELD AND POOL, OR WILDCAT Diamondtail Bone Spring	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 11, 23S, 32E	
		12. COUNTY OR PARISH Lea	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Subsequent Report of P&A Procedure

1. POH w/ rods, pump & tubing.
2. Set CIBP @ 9860' & capped w/ 35' cement.
3. Displaced hole w/370 bbl. 10# brine & salt gel.
4. Set 150' cement plugs @ 8650' & 7075'.
5. Set 100' cement plugs @ 4905', 2900', 1300' & 650'.
6. Set 50' cement plug @ surface, cut off wellhead and installed dry hole marker.
7. Have not plowed and reseeded location pending possible third party re-entry attempt.

18. I hereby certify that the foregoing is true and correct

SIGNED

Michael Redtail

TITLE Vice Pres.

DATE 10-30-86

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

11-3-86

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

PA posted 11-6-86

NOV 10 1986
NOV 10 1986
NOV 10 1986