

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
HOBBS, NEW MEXICO 88240

SUBMIT IN TRIPPLICATE
(Other Instructions
When Applicable)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Gulf Oil Corp.	8. FARM OR LEASE NAME Riste Draw Fed
3. ADDRESS OF OPERATOR P. O. Box 670, Hobbs, NM 88240	9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 660' FSL + 1980' FWL	10. FIELD AND POOL, OR WILDCAT Diamond Tail Bone Springs
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 11-23S-32E
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3728' GL	12. COUNTY OR PARISH Lea
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion or Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Log cmt @ 5100'. Clean out to 4990'. Set cmt ret @ 4958', tot 500#-ok. Could not pump into perms. Push ret to 5058'. Cms clean. Set ^{new} cmt ret @ 4968', tot thg 3000#-ok. Lpd 120.24 Cl H" 5030-45'. Lg 1550#. Cap ret w/10' cmt. Dril cmt + ret to 5058'. Dril old ret + cmt. Dril CIBP @ 8025'. Dril cmt + Clean out. Push old ret @ 8504' to 12,058'. Log 12,000'-9,000'. Perf 11,967-71' w/ (1) JH. Acz w/1700 gals 15% HCL. ISIP 3650#. Swab. Perf 11,261-67', 11,351', 11,401', 11,425', 11,434', 11,486', 11,493', 11,514', 11,523', 11,527', 11,557', 11,593', 11,622', 11,658', 11,678', 11,682', 11,689', 11,700', 11,713', 11,728', 11,741' w/ (2) JH. Acz w/64 lbs 15% HCL + 88 RCNB's. ISIP 5250#. Inac w/80,000 gals gel, RCNB's. ISIP 5130#. GIH w/thg to 11,734. GIH w/pmp + rods.

18. I hereby certify that the foregoing is true and correct

SIGNED R. D. Pite TITLE AREA ENGINEER DATE 5-24-85

(This space for Federal or State office use)

APPROVED BY ACCEPTED FOR RECORD TITLE DATE
CONDITIONS OF APPROVAL, IF ANY:

MAY 31 1985 *See Instructions on Reverse Side

RECEIVED

JUN - 5 1985

C.C.F.
HOUSE OFFICE