

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

WATER CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. 983-2	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- WIW		7. Unit Agreement Name
2. Name of Operator Sun Exploration & Production Co.		8. Farm or Lease Name State "A" A/C-1
3. Address of Operator P. O. Box 1861, Midland, Texas 79702		9. Well No. 118
4. Location of Well UNIT LETTER 0, 1295 FEET FROM THE South LINE AND 2615 FEET FROM THE East LINE, SECTION 3 TOWNSHIP 23-S RANGE 36-E NMPM.		10. Field and Pool, or Wildcat Langlie Mattix Seven Rivers Queen
15. Elevation (Show whether DF, RT, GR, etc.) 3462' GR		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER Clean out fill to PBTD prior to scheduled inj. profiles <input checked="" type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Order No. WFX-522 dated 7-17-84

1. MIRU. NU BOP.
2. RIse pkr & POH w/2-3/8" cmt lined tbq & Pkr.
3. RIH w/4-3/4" bit on 2-3/8" WS & cln out fill 3772'-3815' (PB).
4. Catch samples of returns and submit to PSL for analysis.
5. Circ hole clean. POH.
6. RIH w/ pkr & 2-3/8 CL tbq. Set pkr @ 3540'.
7. Return well to injection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Maria L. Perez TITLE A/C915-688-0375 Sr. Acctng. Asst. DATE 3-24-86

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT SUPERVISOR TITLE  DATE MAR 26 1986

CONDITIONS OF APPROVAL, IF ANY: