Form 9-331 (May 1963) [	ITED STATES DEPARTMENT OF THE INTERIC	SUBMIT IN T) ICATE. (Other instructions on re- verse side)	Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.
	GEOLOGICAL SURVEY		NM 0.552659-A
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals.)			C. JF INDIAN, ALLOTTEE OR TRIBE NAME
1.			7. UNIT AGREEMENT NAME
WELL CAS	OTHER		
2. NAME OF OPERATOR			S. FARM OR LEASE NAME
RIATA CIL & GAS COMPANY 3. Address of Operator			<u>Qurry</u> Federal
<ul> <li>P. O. BOX 5596, Midland, Texas 79704</li> <li>LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface</li> </ul>			
			10. FIELD AND POOL, OR WILDCAT
			Antelope Ridge (Morrow)
1680' FSL & 760; FEL of SEction 22, T23S, R34E.			11. SEC. T. R. M. OR HLK. AND SURVEY OR ARKA SEC. 22-T23S-R34E NMPM
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, B	нт, GH, etc.)	12. COUNTY OR PARISH 13. STATE
	GL 3415.5		Lea New Mexico
16.	Check Appropriate Box To Indicate Na	ture of Notice, Report, or C	Other Data
NOT	NCE OF INTENTION TO :		UENT REPORT OF
TEST WATER SHUT-OFF	FULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
SHOOT ON ACIDIZE REPAIR WELL	ABANDON*	SHOOTING OR ACIDIZING	ABANDON MENTI
(Other)		(Other) (Nore: Report results	of multiple completion Well
17. DESCRIBE PROPOSED OR CO proposed work. If we nent to this work.) *	OMPLETED OPERATIONS (Clearly state all pertinent ell is directionally drilled, give subsurface locatio	details, and give pertinent dates, as and measured and true vertice	Including estimated date of starting any including estimated date of starting any including the markers and zones perti-
(Open hole determine d casing line 1. Th	oject well was blown down from a static as estimated to be producing at the rat 13,359' - 13,295'. The well did no if the borehole was clear and an obstru r. Subsequent milling and fishing oper the 5 1/2" OD liner (P-110, 8 Rd, LT& de in November 1996 Diete Gil & Se	e of 80–100 MCFPD from the t flow any liquids. A wi ction was found at 11,655' ations established the fol C) had collapsed when an a	Morrow formation reline was run to in the 5 1/2" OD lowing facts: ttempt to treat the
joint (11,6	de in November, 1984. Riata Oil & Ga iner had collapsed between the top of t 542'-11715'), thae entire interval of r overlap (the 7 5/8" casing was set at	he fourth joint and the mine the collapsed casion was	ddle of the fifth
TOL LOOL I	fter milling through the collapsed casi re-entry and the entire liner was pre- The damaged area was effectively cased .	ssure tested to 2.800 osi	without loss of
3. Th is no longer	ne permanent packer body that had previ r in the well. The open hole section w	ously been set at 13,270' a as cleaned out to a depth a	was drilled out and of 13,322'.
nichte asseu	n Elder Model "E" permanent packer on 2 mbly on tubing, testing tubing to 8,500 3,500 psi., OK.	7/8" OD tubing and set at O psi. Nippled up wellhe:	13,242'. Ran seal ad for production,
18. J hereby certify that the	foregoing strue and correct		<u>* - 12.6 (2.8) (3.8) (2.8)</u>
SIGNED	31/ C	tont for Dista of	
(This space for Federal		Jent for Riata Oi	
			医球合脑病 装饰 医白色碱
APPROVED BY TITLE TITLE			DATE DATE
	*See Instructions of	on Reverse Side	1. 高橋台。 11. 日本教育 11. 日本教育 11. 日本教育



•