

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. OIL CONS. COMMISSION
P.O. BOX 1980
HOBBS, NEW MEXICO 88240

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT --" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well: ☒ OIL WELL ☐ GAS WELL ☐ OTHER

2. Name of Operator
TEXACO EXPLORATION & PRODUCTION INC

3. Address and Telephone No. P.O. BOX 730, HOBBS, NM 88240 397-0426

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
Unit Letter K : 1980 Feet From The SOUTH Line and 1980 Feet From The
WEST Line Section 33 Township 22S Range 38E

5. State Oil / Gas Lease No.

LC032104

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and Number

A H BLINEBRY FEDERAL NCT 1

42

9. API Well No.

30 025 28823

10. Field and Pool, Exploratory Area
BRUNSON DRINKARD ABO, SOUTH

11. County or Parish, State

LEA, NEW MEXICO

12. Check Appropriate Box(s) To Indicate Nature of Notice, Report, or Other Data

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ OTHER: FRACTURE TREATMENT
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log Form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true verticle depths for all markers and zones pertinent to this work.).

- 1). RUPU and install BOP. TOH w/pumping equipment.
- 2). Tag @ 6730' and clean out w/bailer if neccessary.
- 3). Perforate from 6583'-6593'.
- 4). Set RBP @ 6720'. POH and set pkr @ 6710'. POH and set pkr at 6400'. Dump 10' sand on RBP.
- 5). Fracture perf's from 6450'-6680' w/68,500 gals gel 200,000# sand (Max TP 8,000#)
- 6). Release pkr and POH w/tbg. RIH w/5 1/2" bit and clean out to 6720'. Reverse sand of RPB. Retrieve plug. TOH w/tbg.
- 7). Release pkr and POH w/tbg. RIH w/5 1/2" bit and clean out to 6720'. Reverse sand of RPB. Retrieve plug. TOH w/tbg.
- 8). Place well on production.

RECEIVED
FEB 4 11 30 AM '94
CARL AREA

14. I hereby certify that the foregoing is true and correct

SIGNATURE Larry W. Johnson TITLE Engr Asst DATE 2/3/94

TYPE OR PRINT NAME Larry W. Johnson

(This space for Federal or State office use)

APPROVED BY (ORIG. SGD.) JOE G. LARA TITLE PETROLEUM ENGINEER DATE 2/17/94

CONDITIONS OF APPROVAL, IF ANY:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.