

UNIT STATES DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> P&A	5. LEASE DESIGNATION AND SERIAL NO. NM 38469
2. NAME OF OPERATOR Yates Petroleum Corporation	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR 207 South 4th St., Artesia, NM 88210	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 330 FSL & 1650 FEL, Sec. 30-T23S-R34E	8. FARM OR LEASE NAME Kestrel ABE Federal
14. PERMIT NO.	9. WELL NO. 1
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3629' GR	10. FIELD AND POOL, OR WILDCAT Und. Bell Lake Bone Springs
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Unit 0, Sec. 30-T23S-R34E
	12. COUNTY OR PARISH Lea
	13. STATE NM

18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

PULL OR ALTER CASING ☐

WATER SHUT-OFF ☐

REPAIRING WELL ☐

FRACTURE TREAT ☐

MULTIPLE COMPLETION ☐

FRACTURE TREATMENT ☐

ALTERING CASING ☐

SHOOT OR ACIDIZE ☐

ABANDON\* ☐

SHOOTING OR ACIDIZING ☐

ABANDONMENT\* ☒

REPAIR WELL ☐

CHANGE PLANE ☐

(Other) ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Plugged and abandoned well as follows:

Set CIBP at 8650' w/35' cement on top.

Set CIBP at 7300' w/35' cement on top.

Set CIBP at 5150'. - Cut 5 1/2" casing at 4790' and 4625'. Could not pull casing.

Cut 5 1/2" casing at 4020' and pulled 96 jts and 2 cutoffs.

Set plugs as follows:

Plug #1 5150-4575' Cemented with 60 sx Class "C".

Plug #2 4070-3970' Cemented with 35 sx Class "C".

Plug #3 1817-1717' Cemented with 35 sx Class "C".

Plug #4 806-706' Cemented with 35 sx Class "C".

Plug #4 Surface Cemented with 10 sx Class "C".

Installed dry hole marker.

Plugging completed 10-10-85.

Verbal permission for plugging given by Mr. Bob Pitsche, BLM, Carlsbad, NM on 6-5-85.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature]

TITLE Production Supervisor

DATE 10-15-85

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side