

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	N. M. OIL CONS. COMMISSION P. O. BOX 1000 HOBBS, NEW MEXICO 88240	5. LEASE DESIGNATION AND SERIAL NO. NM 38469
2. NAME OF OPERATOR Yates Petroleum Corporation		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR 207 South 4th St., Artesia, NM 88210		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660 FSL & 660 FEL, Sec. 19-T23S-R34E		8. FARM OR LEASE NAME Lark ABU Federal
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3570' GR	9. WELL NO. 1
		10. FIELD AND POOL, OR WILDCAT Und. Bell Lake Bone Springs
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Unit P, Sec. 19-23S-34E
		12. COUNTY OR PARISH Lea
		13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Drilling w/cable tools

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

4-17-85. TD 241'- Made 3'.
4-18-85. TD 244' Made 3'.
4-19-85. TD 247. Made 3'.
4-20-22-85. TD 250' Made 3'.
4-23-85. TD 253'. Made 3'.
4-24-85. TD 256'. Made 3'. Lost circulation problems at 240-248' (dry drilling).
4-25-85. TD 259'. Made 3'.
4-26-85. TD 262'. Made 3'.
4-27-29-85. TD 265'. Made 3'. Getting circulation back.
4-30-85. TD 268'. Made 3'.
5-1-85. TD 271'. Made 3'.
5-2-85. TD 274'. Made 3'.
5-3-85. TD 277'. Made 3'.
5-4-6-85. TD 277'.
5-7-85. TD 280'. Made 3'.
5-8-85. TD 283'. Made 3'.
5-9-85. TD 286'. Made 3'.
5-10-85. TD 289'. Made 3'.
5-11-13-85. TD 292'. Made 3'.
5-14-85. TD 298'. Made 6'.
5-15-85. TD 301'. Made 3'.

18. I hereby certify that the foregoing is true and correct

SIGNED Quinta Goodlett TITLE Production Supervisor

DATE 5-15-85

(This space for Federal or State office use)

APPROVED BY ACCEPTED FOR RECORD

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

MAY 31 1985

*See Instructions on Reverse Side

047038 60103192 024

RECEIVED

JUN - 3 1985

O.C.D.
HOBBS OFFICE

024200 1001 048200 40