Form 3100-5
(November 1983)
(Formerly 9-331)

14. PERMIT NO.

## UN' D STATES DEPARTMEN, OF THE INTERIOR

	SUBMIT	IN	TRIPI
	(Other )	nstr	uctions
•	verse aide	• )	

TE.

Budget Burger N 1004= Expires August 31, 1985 د ا ج

EXP	nes	nugust	1 - 1	1000
LEASE	DESI	GNATION	AND	SERIA

12. COUNTY OR PARISH 13. STATE

NM

EXP	HES HURASI	- 2 L .	1000
LEASE	DESIGNATION	AND	SERIAL
LC-0	030133(b	)	

8 IF INDIAN, ALLOTTEE OR TRIBE NAME

BUREAU OF LAN	) MANAGEMENT
---------------	--------------

SHINDRY	NOTICES	AND	<b>REPORTS</b>	ON	WELLS
ALIINIJK I	INCLI	$\neg$ 11 $\nu$	IVE: OIVIO	•	1.6

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT" for such proposals.)

Use "APPLICATION FOR PERMIT—" for such proposals.)	
	7. UNIT AGREEMENT NAME
OIL X GAS WELL OTHER	8. FARM OR LEASE NAME
ARCO Oil and Gas Company	Langley Meyers
P. O. Box 1610, Midland, Texas 79702 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*	1 10. FIELD AND POOL OR WILDCAT
See also space 17 below.) At surface 1880' FNL & 1650 FEL (Unit LEtter G)	Langley Strawn 11. SEC., T., E., M., OR BLE. AND SURVEY OR AREA
	28-22S-36E

	30-025-29295 3517.6 RKB	Lea
6	Check Appropriate Box To Indicate Nature of Notice, Report, or Oth	er Data

15 ELEVATIONS (Show whether DF, RT, GR. etc.)

NO	NOTICE OF INTENTION TO: SUBSEQUENT ESPORT OF:		IPORT OF:		
			r		
TEST WATER SHUT-OF	•	PULL OR ALTER CASINO	G	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT	. —	MILITIPLE COMPLETE		FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE	-	ABANDON*		SHOOTING OR ACIDIZING	ABANDONMENT* X
REPAIR WELL	1	CHANGE PLANS		Other) Note: Report results of mu	Itipie completion on Well
-Other)			1	Completion or Recompletion F	leport and Log form

17 DESCRIBE PROPOSED OR COMPLETE OFFRATIONS (Clearly state all pertinent details and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1-29-87 RUPU. POH w/RBP. P&A'd as follows:

Plug	Interval	Cmt	Remarks
	5700-5800	30sx	CIBP @ 5800. 30sx spotted.
2	2900-3814	270sx	Spot. WOC. Tag TOC @ 2900.
3	1060-1400	125sx	Perf @ 1400. CR @ 1200 w/40sx on top.
Λ	0- 55	70sx	Perf @ 55. Cmt inside & outside 8-5/8.

Install P&A marker. Well P&A'd 1-30-87

hereby certify that the foregoing is true and correct	915-688-5672 TITLE Engr. Tech. Spec.	<b>DATE</b> 3-3-87
This space for Federal or State office use)  PPROVED BY	TITLE	DATE 3.20 87
Ett.		

\*See Instructions on Reverse Side

MAR 2.3 1987

MAR 2.3 1987

MAR SOFFICE

HOBBS OFFICE