

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

LC - 032104

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

TEXACO INC

3. ADDRESS OF OPERATOR

P.O. BOX 728, HOBBS, NEW MEXICO 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

UNIT LETTER E, 1980' FNL & 450' FWL

14. PERMIT NO. API NO.

30-025-29353

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3390 KB

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

A.H. BLUNERY FED. NCT-1

9. WELL NO.

43

10. FIELD AND POOL, OR WILDCAT

SOUTH BRUNSON DRINKARD ABO

11. SEC., T., R., M., OR B.L. AND SURVEY OR AREA

SEC 33, T-22S, R-38E

12. COUNTY OR PARISH

LEA

13. STATE

NEW MEXICO

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. ON FEBRUARY 20, 1989. MIRU. PULL RODS AND PUMP. TAG FILL AT 7456. TOH W/TUBING.
2. 61H AND SET RETRIEVABLE BRIDGE PLUG AT 6645' TOH.
3. PERFORATED SOUTH BRUNSON DRINKARD ABO AT 6407'-09', 50'-54', 76'-78', 6500'-01', 06'-07', 29'-31', 34', 36'-40', 86'-89', 95'-97', 6602'-05', AND 6620'-24'; 40 INTERVALS, 2 SPI, 80 SHOTS.
4. TIH W/PACKER. SET PACKER AT 6197'. ACIDIZE PERFORATIONS WITH 5000 GALLONS 15% NEFE HCL WITH 100 BALL SEALERS. MAX PRESS 2700 PSI, AVE RATE 4 BPM, ISIP 1500 PSI.
5. SWABBED 55 BBLs BACK.
6. FRAC PERFORATIONS WITH 24,000 GALS 20% NEFE ACID, 24,000 GALLONS 40% GELLED PAD, 18,000 LBS OF 100 MESH SAND, MAX PRESS 4000 PSI, AVE PRESS 3200 PSI, RATE 14.5 BPM.
7. S.I. 1 HR, T.P. 1400 PSI, FLOWBACK 227 BBLs
8. RELEASE PKR AND TOH. TIH AND RETRIEVED B.P.
9. RAN PRODUCTION EQUIPMENT
10. PUT WELL ON TEST.
11. 24 HR POTENTIAL ENDING AT 10:00 A.M. MARCH 6, 1989

24 P 52°/48°/2308^{GOR}, 120^{MCF} GRAVITY 37° & 60°F

18. I hereby certify that the foregoing is true and correct

SIGNED

KL Johnson

TITLE AREA SUPERINTENDENT

DATE

MAR 6 1989

(This space for Federal or State office use)

APPROVED BY

RECORDED
(OFFICIAL) DAVID R. GLASS

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY

CARLSBAD, NEW MEXICO

*See Instructions on Reverse Side

RECEIVED

MAR 16 1989

GOV
HOBBS OFFICE