

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-025-29469
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Lou Worthan
8. Well No. 19
9. Pool name or Wildcat Wantz Abo

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☐ GAS WELL ☒ OTHER	
2. Name of Operator Marathon Oil Company	
3. Address of Operator P.O. Box 2409 Hobbs, NM 88240	
4. Well Location Unit Letter D : 680 Feet From The North Line and 880 Feet From The West Line Section 11 Township 22-S Range 37-E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GL 3368 KB 3382	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: **Add Abo Perfs. Stimulate. Artificial Lift** ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU pulling unit. ND wellhead. NU BOP. Rel TAC and POOH. POOH w/tbg. PU RBP. GIH to 63'. Test BOP and POOH. RIH w/csg scrapper to 7000'. POOH. RIH w/RBP and set at 6500'. Pickle tbg w/700 gals 15% HCL. Rel RBP and GIH to 6870, reset RBP.

Perforate Abo w/2 JSPF, 120 deg phasing from 6546-56', 6574-94', 6611-16', 6615-28', 6631-34', 6650-65', 6675-82', 6692-95', 6698-6702', 6710-16', 6726-38', 6744-46', 6754-57', 6762-68', 6772-78', 6782-85', 6794-97', 6802-12', 6818-24', 6834-40', 264 total holes. RIH w/pkr, set at 6860'. Test RBP. PUH and reset pkr at 6505'. Acidize Abo w/10,000 gals 15% acid. Swabbed well.

Rel pkr at 6505'. RIH latch onto RBP. POOH w/pkr and RBP. RIH w/2 3/8" production tbg. SN at 7009'. TAC at 6505'. ND BOP. NU wellhead. RIH w/pump and rods. RD pulling unit.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kelly Cook TITLE Records Processor DATE 8/26/97

TYPE OR PRINT NAME Kelly Cook TELEPHONE NO. 393-7106

(This space for State Use)

ORIGINAL SIGNED BY CHRIS WILLIAMS
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-025-29469
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Lou Worthan
8. Well No. 19
9. Pool name or Wildcat Wantz Abo

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☐ GAS WELL ☒ OTHER	
2. Name of Operator Marathon Oil Company	
3. Address of Operator P.O. Box 2409 Hobbs, NM 88240	
4. Well Location Unit Letter D : 680 Feet From The North Line and 880 Feet From The West Line Section 11 Township 22-S Range 37-E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GL 3368 KB 3382	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: Add Abo Perfs. Stimulate. Artificial Lift ☒	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU pulling unit. ND wellhead. NU BOP. POOH w/tbg. RIH w/RBP & set at 100'. RIH w/pkr & set at 80'. Pressure test. Rel pkr. POOH. RIH, rel RBP. POOH. RIH w/bit & scrapper, tag PBTD at 7050'. POOH. RIH w/RBP & set at 6500'. Pickle tbg w/700 gals 15% acid. Rev spent acid. Rel RBP & reset at 6870'. RU wireline. Selectively perf Abo formation w/2JSPF. 120 deg phasing at 6546-56', 6574-94', 6611-16', 6625-28', 6631-35', 6631-34', 6650-64', 6675-82', 6692-95', 6698-6702', 6710-16', 6726-38', 6744-46', 6754-57', 6762-68', 6772-78', 6782-85', 6794-97', 6802-12', 6818-24', 6834-40'. (264 holes). RD wireline. RIH w/RBP overshot & pkr. Set pkr at 6860'. Pressure test. Rel pkr & reset at 6500'. RU acid company. Acidize Abo formation 6976-7070' w/9900 gals 15% acid & 400 1.3 SG ball sealers. Swab back acid load. Rel pkr at 6500'. Rel RBP at 6870'. POOH w/pkr and RBP. RIH w/ 2 3/8" production tbg to 7030'. SN at 7009'. TAC at 6500'. ND BOP. Set TAC. NU wellhead. RIH w/pump and 3/4" rods. RDMO pulling unit. Start well pumping.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kelly Cook TITLE Records Processor DATE 8/7/97
TYPE OR PRINT NAME Kelly Cook TELEPHONE NO. 393-7106

(This space for State Use)

ORIGINAL SIGNED BY CHRIS WILLIAMS
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE 808 19 1997
CONDITIONS OF APPROVAL, IF ANY: