STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

40. 07 \$001E0 ACCEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

CONSERVATION DIVISION

	40. 07 \$00160 BCCCIVED		TION DIVISION		
	DISTRIBUTION	P. O. BO.	X 2088		Form C-103 Revised 10-1-78
	SANTA FE] SANTA FE, NEW	MEXICO 87501		KG41250 10-1-10
	FILE			5a. Indicate Typ	o of Leuse
	U.S.O.S.			State	Fee X
	LAND OFFICE				
	OPERATOR			5. State Oil & G	ds Ledse No.
	SUNDS	RY NOTICES AND REPORTS ON OPOSALS TO ORILL OR TO DEEPEN OF PLUG B	WELLS ACT TO A DIFFERENT RESERVOIR. H PROPOSALS.)		
•	OIL X GAB WELL	OTHER-		7, Unit Agreeme	nt Name .
. N	aine of Operator			8, Form or Leus	e liame
• • •	Marathon Oil Com	nany		Lou Worth	an
	ddress of Operator	Pung		9. Well No.	
. ^	•	Hobbs, NM 88240		19	
. L	ocation of Well			10. Field and Po	ool, or Wildcat
	D	680 FEET FROM THE North	880	Wantz Abo	
	UNIT LETTER	PEET FROM THE		1111111	
	THE West LINE, SECTI	10N 11 TOWNSHIP 22S	HANGE 37E NM	··· (
					<i>1111111111</i>
7		15. Elevation (Show whether	DF, RT, GR, etc.)	12. County	
1		GR 3368', KB	3382'	Lea	
۲ς:	Clark	Appropriate Box To Indicate N		Jther Date	
				NT REPORT OF	•
	NOTICE OF I	NTENTION TO:	30532002	INT KEI OKT OF	•
-	FORM REMIDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK		RING CASING
7 E h	PORARILY ABANDON		COMMENCE DRILLING OPHS.	700	
PUL	L OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	norations	x
		<u> </u>	OTHER Completion O	DET & CTOHS	
	OTHER				
	·		ails, and give pertinent dates, includ		

Purpose: Abandon Granite Wash and Test Lower Wantz Abo.

On January 20, 1986 a CIBP was set at 7050' to abandon the Wantz Granite Wash (7069' - 7110'). The Granite Wash was unproductive.

The lower Wantz Abo was perforated at 6765, 73, 95, 6808, 19, 35, 89, 6941, 58, 77, 98, 7010, 24 with 1 JSPF (13 holes). On January 21, 1986 this zone was acidized with 3500 gallons 15% HCl. The well is now being swab tested.

best of my knowledge and belief.
Production Engineer 01-22-86
JAN 2 4 1986