## STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

		11416
44. 07 E4*1E8 RECEIVES		
DISTRIBUTION		
BANTA FE	1	
FILE		
U.S.O.S.		
LAND OFFICE		
OPERATOR	T	

DISTRIBUTION			
	Р. О. ВО		Form C-103
BANTA PE	SANTA FE, NEV	V MEXICO 87501	Revised 10-1-78
FILE	<u> </u>		5a. Indicate Type of Lease
U.S.O.S.	4		State X Fee
LAND OFFICE	-		
OPERATOR	j		5. State Oil & Gas Lease No.
			B-229
IDO NOT USE THIS FORM FOR PR	RY NOTICES AND REPORTS ON	BACK TO A DIFFERENT RESERVOIR.	
	TION FOR PERMIT -" (FORM C-101) FOR SU	CH PROPOSALS.)	7 154 Assessment Nove
OIL X WELL	OTHER-		7. Unit Agreement Name
. 2. Name of Operator			8. Form or Lease Name
ARCO Oil and Gas Co.	- A Division of Atlanti	c Richfield Co	Seven Rivers Queen Unit
3. Address of Operator			9. Well No.
P.O. Box 1610, Midla	ind, Texas 79702		71
14. Location of Well		<del></del>	10. Field and Pool, or Wildcat
unit LETTER B	1310 North	2480 FEET PR	Langlie Mattix RQ
THE East LINE, SECT	10H TOWNSHIP 23	S RANGE 36E NMP	//////////////////////////////////////
	15. Elevation (Show whether	DF, RT, GR, etc.)	12. County
	3463.5 GR		Lea ()
	Appropriate Box To Indicate I	· ·	other Data
PERFORM REMEDIAL WORK	PLUE AND ABANDON	REMEDIAL WORK	ALTERING CASING
Ä		1 =====================================	<u> </u>
TEMPORARILY ASANDON		COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOS X	
		отня <u>5-1/2" Produc</u>	tion Casing String
OTHER	[		
	perations (Clearly state all pertinent des	tails, and give pertinent dates, includi	ng estimated date of starting any proposed
work) SEE RULE 1103.			
		•	
Ran 5-1/2" csg 1-5-1	l/2" F <b>5</b> @ 3870', 1 jt 5-1	/2" 15.5# K-55 STC 8rd,	1-5-1/2" FC @ 3825'
	@ 3852', 3792', 3708', 3		
3			J . Land CSg @ JO/U
			J. Land Csg @ 3070
	O sx LW IV C1 "H" w/1/4#/		1#), 250 sx C1 "H"
	O sx LW IV C1 "H" w/1/4#/ own @ 0630, 11-2-86. ND		1#), 250 sx C1 "H"
			1#), 250 sx C1 "H"
			1#), 250 sx C1 "H"
			1#), 250 sx C1 "H"
			1#), 250 sx C1 "H"
			1#), 250 sx C1 "H"
			1#), 250 sx C1 "H"
			1#), 250 sx C1 "H"
			1#), 250 sx C1 "H"
			1#), 250 sx C1 "H"
			1#), 250 sx C1 "H"
			1#), 250 sx C1 "H"
			1#), 250 sx C1 "H"
		BOPE, set slips the data	1#), 250 sx C1 "H"
Neat 16.4#. Plug do		BOPE, set slips the data	1#), 250 sx C1 "H"
Neat 16.4#. Plug do	own @ 0630, 11-2-86. ND	BOPE, set slips the data	1#), 250 sx C1 "H"
Neat 16.4#. Plug do	own @ 0630, 11-2-86. ND	BOPE, set slips the date of my knowledge and belief.	1#), 250 sx C1 "H" nd test to 1500# OK.
Neat 16.4#. Plug do	own @ 0630, 11-2-86. ND	BOPE, set slips the data	1#), 250 sx C1 "H"
Neat 16.4#. Plug do	own @ 0630, 11-2-86. ND	BOPE, set slips the date of my knowledge and belief.	1#), 250 sx C1 "H"  nd test to 1500# OK.
Neat 16.4#. Plug do	own @ 0630, 11-2-86. ND	BOPE, set slips the date of my knowledge and belief.	1#), 250 sx C1 "H"  nd test to 1500# OK.