

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease  
State ☐ Fee ☒  
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator Exxon Corporation Attn: David A. Murray 3. Address of Operator P. O. Box 1600, Midland, TX 79702 4. Location of Well UNIT LETTER <u>A</u> <u>350</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>13</u> TOWNSHIP <u>22S</u> RANGE <u>37E</u> NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 3327' GR	7. Unit Agreement Name 8. Farm or Lease Name N. G. Penrose 9. Well No. 4 10. Field and Pool, or Wildcat Wantz Granite Wash 12. County Lea
---	---

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <u>MIRU comp. rig and csg test</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-8-87 MIRU well service unit and NU BOPs

9-9-87 Drill cmt. and FC to 7553', circ. csg. clean and test csg. and BOPs to 500# - OK.  
Begin completion operations.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.  
David A. Murray

SIGNED David A. Murray TITLE Permits Supervisor DATE 9-18-87

Eddie W. Seay

Oil & Gas Inspector

APPROVED BY Eddie W. Seay TITLE Oil & Gas Inspector DATE SEP 23 1987

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

SEP 22 1981

OCD  
HOBBS OFFICE