

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-30742
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name Seven Rivers Queen Unit	
8. Well No.	76
9. Pool name or Wildcat	Eunice 7RQ, South
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3510 GR	

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. Name of Operator ARCO OIL AND GAS COMPANY
3. Address of Operator P. O. Box 1610, Midland, Texas 79702	4. Well Location Unit Letter <u>G</u> : <u>2575</u> Feet From The <u>North</u> Line and <u>1590</u> Feet From The <u>East</u> Line Section <u>34</u> Township <u>22S</u> Range <u>36E</u> NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3510 GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☒  
OTHER: Complete ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD'd 7 7/8 hole at 3850, 1-1-90. Ran GR-CCL-DSN-SDL. Ran 5 1/2 15.5# J-55 csg to 3842. Cmt'd w/575 sx Howco lite followed by 275 sx "C" Neat. Circ cmt to surf. RR 1-2-90.

1-11-90. RU PU. tag cmt at 3752. DO cmt to 3810 PBD. press test csg to 3000# for 30 min. Perf f/3682-3760. Acidize Queen perfs w/1200 gals. frac w/30,000 gals & 97,500# sd. Swab load. RIH w/CA: 2 3/8 tbq to 3613. Ran pump & rods. RDPU. 1-17-90.

1-22-90. In 24 hrs pmpd 93 BO 276 BW 24 MCF.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ken W. Gosnell TITLE Engr. Tech. DATE 1-24-90  
TYPE OR PRINT NAME Ken W. Gosnell 915/688-5672 TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

JAN 30 1990

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: