

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240
DISTRICT II
P.O. Drawer Dd, Artesia, NM 88210
DISTRICT III
1000 Rio Brazos Rd., Aztec, Nm 87410

API NO. (assigned by OCD on New Wells) 30-025-31388	
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>	
6. State Oil & Gas Lease No. N/A	
7. Lease Name or Unit Agreement Name ARROWHEAD GRAYBURG UNIT	
8. Well No. 212	
9. Pool name or Wildcat ARROWHEAD /GB	
10. Elevation(Show whether DF, RKB, RT, GR, etc.) 3436 GE	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL <input type="checkbox"/> GAS <input type="checkbox"/> WELL <input type="checkbox"/> WELL <input type="checkbox"/> OTHER <input type="checkbox"/> INJECTOR	
2. Name of Operator CHEVRON U.S.A. INC.	
3. Address of Operator P.O. BOX 1150 MIDLAND, TX 79702 ATTN: P.R. MATTHEWS	
4. Well Location Unit Letter M : 630 Feet From The SOUTH Line and 660 Feet From The WEST Line Section 7 Township 22S Range 37E NMPM LEA County	
10. Elevation(Show whether DF, RKB, RT, GR, etc.) 3436 GE	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CMT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: COMPLETION <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU, TIH TO 3633'.
DRILL OUT CEMENT TO 3791' AND TEST CASING TO 1000 PSI-OK.
LOG HOLE: CBL-CET-GR-CCL.
PERFORATE WITH 2 JHPF, 180 DEG. PHSD, 4" GUNS AT 36126-3704, 24 HOLES.
ACDZ PERFS WITH 200 GALS OF 15% NEFE, SWAB BACK ACID.
PERF WITH 4" GUNS, 180 DEG. PHSD, 72 HOLES AT 3616-3774.
ACDZ 3616-3786 WITH 400 GALS OF 15% NEFE. TOH.
TIH WITH INJECTION TBG. AND PACKER, SET AT 3586'.
LOAD BACK SIDE WITH PACKER FLUID AND TEST TO 500 PSI-OK.
RIG DOWN MOVE OUT ON 2-26-92.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE <u>P.R. Matthews</u>	TITLE <u>TECH. ASSISTANT</u>
DATE: <u>3/6/92</u>	
TYPE OR PRINT NAME <u>P.R. MATTHEWS</u>	TELEPHONE NO. <u>(915)687-7812</u>
APPROVED BY _____	TITLE _____
DATE: <u>MAR 10 '92</u>	
CONDITIONS OF APPROVAL, IF ANY:	